

## Tank Battery : South



## Tank Battery : West



This is an orphaned well inspection. Inspection completed to document current condition of location, equipment, and wellhead. Inspection may also identify possible task required for final closure/release of location from the Orphaned Well Program.

Inspection Number: **709200078**

## Tank Battery : Sign





**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos

**SITE NAME**

Location ID: **#**

## LISCO 14-32 Well Head : North



## LISCO 14-32 Well Head : East



Inspection Number: **709200078**





**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos

**LISCO 14-32**

Location ID: **320063**

## LISCO 14-32 Well Head: South



## LISCO 14-32 Well Head: West



Inspection Number: **709200078**



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos

**C LISCO 14-31**

Location ID: **320104**

**C LISCO 14-31 Well Head : North**



**C LISCO 14-31 Well Head : East**



Inspection Number: **709200078**





**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos

**C LISCO 14-31**

Location ID: **320104**

**C LISCO 14-31 Well Head: South**



**C LISCO 14-31 Well Head: West**



Inspection Number: **709200078**



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos

**C LISCO 14-31**

Location ID: **320104**

## C LISCO 14-31 Well Head: Sign



Inspection Number: **709200078**



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos

**C LISCO 14-21**

Location ID: **320087**

## C LISCO 14-21 Well Head : Zoomed in from fence



## C LISCO 14-21 Well Head : from outside Colorado Air & Spaceport fence



Inspection Number: **709200078**