

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/15/2024

Submitted Date:

02/20/2024

Document Number:

705000629

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
Maclaren, Joe _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Findings:

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Graber, Nikki		nikki.graber@state.co.us	
Peterson, John		jpeter@kpk.com	
		cogcc@kpk.com	
Brown, Kari		kari.oakman@state.co.us	
Anderson, Laurel		laurel.anderson@state.co.us	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
479608	Flowline System	AC	03/12/2021		-	Facility 4 Consolidation	EG

General Comment:

ECMC Engineering Integrity Inspection performed on February 15th, 2024 in response to initial form 19 spill report Doc #403661051 received on 01/19/2024 that outlines: During a routine inspection, a KPK employee discovered the presence of oil surfacing at near the Ditlev-Simonson C1 well. Appropriate personnel were notified, and the line was immediately isolated and remaining fluid was evacuated. Emergency locates were called in and once cleared, crews began excavating to investigate and repair the failed line.

Corrective actions/ information to be submitted bu operator is outlined in the flowline section of report. Photo log is uploaded.

Inspected Facilities

Facility ID: 479608 Type: Flowline API Number: - Status: AC Insp. Status: EG

Flowline

#1	Type: Non-Well Site	of Lines
----	---------------------	----------

Flowline Description

Flowline Type: Non-Well Site Size: 3" Material: Poly
 Variance: Age: Contents: Multiphase

Integrity Summary

Failures: Spills: Yes Repairs Made: Yes
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Yes Test Result: Charted: Yes

COGCC Rules (check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: ECMC Integrity Inspector along with KPK personnel were on location on 02/15/2024. A fenced excavation (measuring approx 30' x 50') was observed @ 40.093323, -104.935819 approximately 40' NE of the Ditlev Simonsen C 1 wellhead. (2) 3" SDR 11 HDPE off location flowlines; and (1) 2" CS natural gas flowline were observed exposed in the excavation. The new HDPE flowlines were recently installed as part of the repair/ pipe replacement completed at spill id #485898. A total of approximately 1500 linear feet of new 3" HDPE flowline pipe has been installed (via slip lining through existing 6" OD CS pipe); from the excavation at wellhead (above) south to an open excavation located at approx 40.090598, -104.935895. The failure of the flowline pipe (6" CS/ Facility 4) resulting in the spill was not seen (repair completed); the root cause is unknown at this time. Excavation and remediation activities are in progress.

Post repair flowline pressure testing was witnessed at the time of this field inspection. The repair segment detailed above was part of the integrity testing. The results of testing will be reviewed by ECMC engineering integrity team upon submittal of chart/ testing data and other misc information from operator.

Corrective Action: Document information requested below in the CA section of ECMC supplemental form 19 spill report to include the following (compliance of COGCC series 1100 flowline rules):
 1) Outline root cause of failure resulting in spill (details/ specifics) (1104.k. Integrity Failure Investigation/Operator Determination)
 2) Measures taken to prevent a recurrence of failure (1104. Integrity Management)
 3) Detailed description of flowline repair work completed (1102.j. Repair)
 4) Confirm integrity of flowline repairs/ reconnections (via pressure testing/ upload chart with test date) prior to returning flowline(s) to service (1102.j.4 and 1102.O)
 *use form 27 to document information if form 19 is closed

Date: 03/05/2024

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
705000631	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6435624