

KP Kauffman - ECMC Inspection Photos
Location: Facility #4 at UPRR 43 Pan Am AE Flowline Release
Spill ID #485940 Date 02/15/2024



Fenced hydro excavation at spill id #485940
Note: Compromised section of Facility 4 pipe is not exposed



Fenced excavation north of flowline release. Flowline repair pipe (HDPE) and existing consolidation lines are exposed.
View looking south on west side of Ridgeway Bd.

KP Kauffman - ECMC Inspection Photos
Location: Facility #4 at UPRR 43 Pan Am AE Flowline Release
Spill ID #485940 Date 02/15/2024



Closer view of flowline repair completed. The existing 6" CS facility #4 flowline transitions to 3" HDPE pipe in both a south and west direction via T fitting/ sliplining. An isolation valve is also present in the excavation.

Fenced excavation at south flowline bellhole; 3" HDPE flowline turns west in the excavation. View looking North.