

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/8NWSW

Location ID: 335619

Date: 2/20/2024



**Location Entrance – Photo #09334**



**Wellhead/Signs Not Posted or Visible – Photo #09335**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/8NWSW

Location ID: 335619

Date: 2/20/2024



Feb 20, 2024 at 10:31:09



Feb 20, 2024 at 10:31:20

Separators – Photo #09338

Tank Battery – Photo #09339



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/8NWSW

Location ID: 335619

Date: 2/20/2024



**Wellhead Signs Not Posted/Visible – Photo #09337**



**Open-Ended Load Line – Photo #09340**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/8NWSW

Location ID: 335619

Date: 2/20/2024



**Lack of Stabilization – Photo #09341**



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit  
– Photo #09342**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/8NWSW

Location ID: 335619

Date: 2/20/2024



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit  
– Photo #09344



Insufficient Administrative Controls – Photo #09343