

Inspection Photos
Location: Weco-William 13-11 # 1
Facility ID: 321674



Photo 1 – Well placard



Photo 2 – Area of historical wellhead. Unused equipment throughout location

Inspection Photos
Location: Weco-William 13-11 # 1
Facility ID: 321674



Photo 3 – Machine Guarding not maintained.

Photo 4 – Unused equipment and debris

Inspection Photos
Location: Weco-William 13-11 # 1
Facility ID: 321674



Photo 5 – Oil stained soils



Photo 6 – Unused equipment, buckets with oily liquids

Inspection Photos
Location: Weco-William 13-11 # 1
Facility ID: 321674



Photo 7 – Oil stained soils, Pumping Unit frame



Photo 8 – Area of potential impacted soils

Inspection Photos
Location: Weco-William 13-11 # 1
Facility ID: 321674



Photo 9 – Placard at Tank Battery



Photo 10 – Soil pile, Fencing/Guarding not maintained

Inspection Photos
Location: Weco-William 13-11 # 1
Facility ID: 321674



Photo 11 – Fencing/Guarding not maintained

Photo 12 – Cement

Inspection Photos
Location: Weco-William 13-11 # 1
Facility ID: 321674



Photo 13 – Soil Pile



Photo 14 – Fencing/Guarding not maintained