

# Inspection Photos

API: 099-06045

Operator: RENEGADE OIL & GAS COMPANY LLC

Inspection Date: 2/21/2024

County: Prowers



## Inspection Photos



**Photo 1.** Facing southeast toward the tank battery. There is a new tank being installed which will need to follow the 603.k.o. requirements. Previous corrective action was not completed.



## Inspection Photos



**Photo 2.** This tank was leaking crude oil at the time of inspection. The operator was immediately notified by phone call. There is no secondary containment to contain the spill as was required by previous inspection.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API: 099-06045 | Date: 2/21/2024

## Inspection Photos



**Photo 3.** Facing northeast at the location.



## Inspection Photos



**Photo 4.** Facing west toward the tank battery which had been significantly remodified and requires secondary containment per Rule 603.o.



## Inspection Photos



**Photo 5.** There is oil that has leak and sprayed out of the wellhead that needs to be cleaned up.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API: 099-06045 | Date: 2/21/2024

## Inspection Photos



**Photo 6.** Facing west at the south side of the location. Red arrow points to the unmarked guyline anchor.



## Inspection Photos



**Photo 7.** Facing southwest at the location. Unused areas of the location are not reclaimed.



## Inspection Photos



**Photo 4.** Aerial view of the location shows unused areas of the location below and to the right of red line could be put back into cropland.

