

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/22/2024

Submitted Date:

02/22/2024

Document Number:

697008950

FIELD INSPECTION FORM

Loc ID 438706 Inspector Name: Peterson, Tom On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 69175
Name of Operator: PDC ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Findings:

12 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		cogccinspection@pdce.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
438703	WELL	PR	05/17/2016	OW	123-40091	Tarin Federal 32Y-404	SI
438704	WELL	PR	05/30/2016	OW	123-40092	Tarin Federal 32W-434	SI
438705	WELL	PR	05/24/2016	OW	123-40093	Tarin Federal 32X-204	SI
438707	WELL	PR	10/01/2016	OW	123-40094	Tarin Federal 32Y-314	SI
438708	WELL	PR	05/30/2016	OW	123-40095	Tarin Federal 32W-234	SI
438709	WELL	PR	05/30/2016	OW	123-40096	Tarin Federal 32X-314	SI
438710	WELL	PR	05/30/2016	OW	123-40097	Tarin Federal 32Y-214	SI
438711	WELL	PR	05/23/2016	OW	123-40098	TARIN FEDERAL 32X-334	SI
453891	TANK BATTERY	AC	01/30/2018		-	Tarin Federal Section 32 HZ battery	SI

General Comment:

This is a routine inspection. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator personnel on location at the time of this field inspection.

Location

Overall Good:

Signs/Marker:

Type	CONTAINERS		
Comment:	Methanol system		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Lease road entrance		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	x 8		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Panel x 8		
Corrective Action:		Date:	

Equipment:

Type: Bird Protectors	# 15		corrective date
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 4		
Comment:	Cureton Midstream calibration cards are current.		
Corrective Action:		Date:	
Type: Pig Station	# 1		

Comment:				
Corrective Action:			Date:	
Type: Flow Line	# 8			
Comment:				
Corrective Action:			Date:	
Type: Prime Mover	# 1			
Comment:	Natural gas engine on VRU			
Corrective Action:			Date:	
Type: Prime Mover	# 2			
Comment:	Electric motors on LACT			
Corrective Action:			Date:	
Type: Ancillary equipment	#			
Comment:	Automation array, solar array, supplied air system, ECD scrubbers, methanol system in secondary containment			
Corrective Action:			Date:	
Type: LACT	# 1			
Comment:				
Corrective Action:			Date:	
Type: VRU	# 1			
Comment:				
Corrective Action:			Date:	
Type: Plunger Lift	# 8			
Comment:				
Corrective Action:			Date:	
Type: Horizontal Heated Separator	# 8			
Comment:				
Corrective Action:			Date:	
Type: Bradenhead	# 8			
Comment:	Bradenhead valves are exposed at surface			
Corrective Action:			Date:	
Type: Gathering Line	# 1			
Comment:				
Corrective Action:			Date:	
Type: Emission Control Device	# 7			
Comment:				
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	OTHER	PBV FIBERGLASS		,
Comment:	210 bbls				

Corrective Action:	Date:
--------------------	-------

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	8	OTHER	STEEL AST		
Comment:	533 bbls				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 438703 Type: WELL API Number: 123-40091 Status: PR Insp. Status: SI

Producing Well

Comment:		
Corrective Action:		Date:

BradenHead

Date of Last Brhd Test: 03/14/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:		
Corrective Action:		Date:

Facility ID: 438704 Type: WELL API Number: 123-40092 Status: PR Insp. Status: SI

Producing Well

Comment:		
Corrective Action:		Date:

BradenHead

Date of Last Brhd Test: 03/14/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 2 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:		
Corrective Action:		Date:

Facility ID: 438705 Type: WELL API Number: 123-40093 Status: PR Insp. Status: SI

Producing Well

Comment:		
Corrective Action:		Date:

BradenHead

Date of Last Brhd Test: 03/14/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:		
Corrective Action:		Date:

Facility ID: 438707 Type: WELL API Number: 123-40094 Status: PR Insp. Status: SI

Producing Well

Comment:		
Corrective Action:		Date:

BradenHead

Date of Last Brhd Test: 03/14/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 3 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

Facility ID: 438708 Type: WELL API Number: 123-40095 Status: PR Insp. Status: SI

Producing Well

Comment: _____

Corrective Action: _____

Date: _____

BradenHead

Date of Last Brhd Test: 03/14/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

Facility ID: 438709 Type: WELL API Number: 123-40096 Status: PR Insp. Status: SI

Producing Well

Comment: _____

Corrective Action: _____

Date: _____

BradenHead

Date of Last Brhd Test: 03/14/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

Facility ID: 438710 Type: WELL API Number: 123-40097 Status: PR Insp. Status: SI

Producing Well

Comment: _____

Corrective Action: _____

Date: _____

BradenHead

Date of Last Brhd Test: 03/14/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

Facility ID: 438711 Type: WELL API Number: 123-40098 Status: PR Insp. Status: SI

Producing Well

Comment:

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 03/14/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 453891 Type: TANK API Number: - Status: AC Insp. Status: SI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Self Inspection	Pass	

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697008951	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6439094