

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/20/2024

Submitted Date:

02/22/2024

Document Number:

708301715

FIELD INSPECTION FORM

Loc ID 335577 Inspector Name: Morris, Matthew On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Findings:

- 8 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, CAERUS		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
282342	WELL	SI	10/01/2023	GW	045-11742	CHEVRON 2B-4D	SI
282343	WELL	PR	03/01/2019	GW	045-11741	CHEVRON 2A-4D	PR
282345	WELL	PR	03/01/2019	GW	045-11740	CHEVRON 8B-5D	PR
282349	WELL	PR	06/01/2023	GW	045-11737	CHEVRON 8C-5D	PR
282353	WELL	PR	05/01/2023	GW	045-11734	CHEVRON 2C-4D	PR
282354	WELL	SI	08/01/2023	GW	045-11749	CHEVRON 2E-4D	SI
282355	WELL	PR	03/01/2019	GW	045-11733	CHEVRON 2D-4D	PR

General Comment:

[COGCC Inspection Report Summary](#)

On 2/20/2024 at approximately 11:20, Compliance Inspector Matthew Morris conducted a follow-up inspection at CAERUS PICEANCE LLC, CHEVRON-66S96W/4SWNW at Location ID #335577 in Garfield County, Colorado.

Normal production operations were observed.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Pipe rail fencing		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Barbed wire fencing		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Barbed wire with safety netting		
Corrective Action:		Date:	

Equipment:

Type: Horizontal Heated Separator	# 6		corrective date
Comment:	Flow line maintenance underway. Open trenching has been fenced off with safety netting.		
Corrective Action:		Date:	

Type: Plunger Lift	# 6		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 6		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 6		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				

Corrective Action:		Date:	
--------------------	--	-------	--

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities					
Facility ID:	282342	Type:	WELL	API Number:	045-11742
		Status:	SI	Insp. Status:	SI
Idle Well					
Purpose:	<input checked="" type="checkbox"/> Shut In	<input type="checkbox"/> Temporarily Abandoned	Reminder: _____		
Comment:	<input style="width: 100%;" type="text"/>				
Corrective Action:	<input style="width: 90%;" type="text"/>				Date: _____
Facility ID:	282343	Type:	WELL	API Number:	045-11741
		Status:	PR	Insp. Status:	PR
Producing Well					
Comment:	<input style="width: 100%;" type="text"/>				
Corrective Action:	<input style="width: 90%;" type="text"/>				Date: _____
Facility ID:	282345	Type:	WELL	API Number:	045-11740
		Status:	PR	Insp. Status:	PR
Producing Well					
Comment:	<input style="width: 100%;" type="text"/>				
Corrective Action:	<input style="width: 90%;" type="text"/>				Date: _____
Facility ID:	282349	Type:	WELL	API Number:	045-11737
		Status:	PR	Insp. Status:	PR
Producing Well					
Comment:	<input style="width: 100%;" type="text"/>				
Corrective Action:	<input style="width: 90%;" type="text"/>				Date: _____
Facility ID:	282353	Type:	WELL	API Number:	045-11734
		Status:	PR	Insp. Status:	PR
Producing Well					
Comment:	<input style="width: 100%;" type="text"/>				
Corrective Action:	<input style="width: 90%;" type="text"/>				Date: _____
Facility ID:	282354	Type:	WELL	API Number:	045-11749
		Status:	SI	Insp. Status:	SI
Idle Well					
Purpose:	<input checked="" type="checkbox"/> Shut In	<input type="checkbox"/> Temporarily Abandoned	Reminder: _____		
Comment:	<input style="width: 100%;" type="text"/>				
Corrective Action:	<input style="width: 90%;" type="text"/>				Date: _____
Facility ID:	282355	Type:	WELL	API Number:	045-11733
		Status:	PR	Insp. Status:	PR
Producing Well					
Comment:	<input style="width: 100%;" type="text"/>				
Corrective Action:	<input style="width: 90%;" type="text"/>				Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
Berms						
Compaction						
		Gravel				
		Culverts				
		Berms				
		Check Dams				
Gravel						
		Rip Rap				
		Compaction				
		Sediment Traps				

Comment: Light gravel and compaction on location and lease road; future stormwater events may create tracking issues.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708301716	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6439812