

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/07/2024

Submitted Date:

02/16/2024

Document Number:

709100221**FIELD INSPECTION FORM**Loc ID 425138 Inspector Name: Heibel, Krystal On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 2001 16TH STREET SUITE 900City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**13 Number of Comments6 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|------------------|-------|---|-----------------------|
| Krystal Heibel | | krystal.heibel@state.co.us | |
| , | | nbl_djbu_inspections@nblenergy.com | ALL INSPECTIONS ONLY |
| Kyle Waggoner | | kyle.waggoner@state.co.us | |
| , | | rbucogccinspectionreports@chevron.onmicrosoft.com | All Inspections |
| Dougherty, Tesla | | tesla.dougherty@chevron.com | Regulatory Specialist |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|----------|--------|-------------|------------|-----------|---------------------------|-------------|
| 425138 | LOCATION | AC | | | - | BADGER FEDERAL LF 04-64HN | EI |
| 425431 | WELL | SI | 12/01/2022 | OW | 123-34384 | BADGER FEDERAL LF 03-64HN | EI |

General Comment:

On Feb 7, 2024, ECMC Environmental Unit Staff Krystal Heibel inspected the Badger Federal LF #04-64HN location (Location ID:425142).

This is an environmental inspection. Photo documentation enclosed. Any corrective actions from previous inspections that have not been addressed are still applicable.

| Location | | | |
|--|--|----------|----------------------------|
| Lease Road: | | | |
| Type | Main | | |
| comment: | Fence is damaged next to cattle guard near entrance. | | |
| Corrective Action | L | Date: | |
| Overall Good: <input type="checkbox"/> | | | |
| Signs/Marker: | | | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Tank label (including the emergency contact number) too small to read at distance | | |
| Corrective Action: | Install sign to comply with Rule 605.h. | Date: | 05/16/2024 |
| Type | | | |
| Comment: | Sign not installed properly. Located on the ground during inspection. | | |
| Corrective Action: | | Date: | |
| Emergency Contact Number: | | | |
| Comment: | <input type="text"/> | | |
| Corrective Action: | <input type="text"/> | | Date: <input type="text"/> |
| Good Housekeeping: | | | |
| Type | WEEDS | | |
| Comment: | Weeds located within secondary containment. | | |
| Corrective Action: | Comply with Rule 606 | Date: | 02/23/2024 |
| Type | TRASH | | |
| Comment: | Trash (broken plastic) observed throughout the location. | | |
| Corrective Action: | Comply with Rule 606 | Date: | 02/23/2024 |
| Overall Good: <input type="checkbox"/> | | | |
| Spills: | | | |
| Type | Area | Volume | |
| Crude Oil | Treater | <= 1 bbl | |
| Comment: | Hydrocarbon observed on concrete base of the vertical treater and on adjacent soils. | | |
| Corrective Action: | Control and contain spills/releases and clean up per Rule 912.a. | | Date: 03/16/2024 |
| In Containment: No | | | |
| Comment: | <input type="text"/> | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | |
| Fencing/: | | | |
| Type | | | |
| Comment: | Evidence of wildlife within secondary containment observed. See photo documentation. | | |
| Corrective Action: | | Date: | |
| Equipment: | | | |
| Type: Other | # 1 | | corrective date |
| Comment: | Pipe next to tank battery not bull plugged | | |

| | | | |
|--------------------|--|-------|------------|
| Corrective Action: | Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e. | Date: | 03/16/2024 |
| Type: Other | # 1 | | |
| Comment: | Wildlife protection devices are not adequate. Wire mesh netting was observed not properly installed on secondary containment to prevent access to wildlife. | | |
| Corrective Action: | Install or repair wildlife protection equipment according to Rule 608. | Date: | 03/16/2024 |

Venting:

| | | | |
|--------------------|--|-------|--|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| Inspected Facilities | | | | | | | | | |
|----------------------|--------|-------|----------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 425138 | Type: | LOCATION | API Number: | - | Status: | AC | Insp. Status: | EI |
| | | | | | | | | | |
| Facility ID: | 425431 | Type: | WELL | API Number: | 123-34384 | Status: | SI | Insp. Status: | EI |
| | | | | | | | | | |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 403690233 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6432347 |
| 709100222 | Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6432313 |