

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/21/2024

Submitted Date:

02/23/2024

Document Number:

713600771**FIELD INSPECTION FORM**Loc ID 321213 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 83130Name of Operator: STRACHAN EXPLORATION INCAddress: 992 S 4TH AVE SUITE 100-461City: BRIGHTON State: CO Zip: 80601**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments5 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
BEAR STACY L		stacy@strachanexploration.com	
HARMS, JASON		jharms@strachanexploration.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
321213	LOCATION	AC			-	BOURNE-622S48W 30SENW	RI

General Comment:

This is a follow up of the previous reclamation inspection #713600504.
The previous inspection corrective actions were not completed.
See attached photos and additional details within this report.

Operator is directed to perform corrective actions outlined on this inspection report immediately.

LocationOverall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:	The sign at the tank battery has the incorrect Operator and is faded. Previous corrective action was not completed.		
Corrective Action:	Install sign to comply with Rule 605.e.	Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	There is an unused pipe riser at the wellhead with no OOSLAT. Previous corrective action was not completed.		
Corrective Action:	Comply with 606.	Date:	
Type	WEEDS		
Comment:	There are tall undesirable weeds at the location that need to be controlled and removed. It appears bare ground treatment was performed however the tall dry weed debris is a fire hazard and needs to be removed. Previous corrective action was not completed.		
Corrective Action:	Comply with Rule 606.	Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
	Separator			
Comment:	There is still a dripping leak at the seperator that has not been controlled. Previous corrective action was not completed and must be addressed immediately.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.			Date:

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	200 BBLs	STEEL AST		,	
Comment:						
Corrective Action:					Date:	

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Inspector Name: COSTA, RYAN

Earth	Inadequate		Inadequate	
Comment:	The secondary containment is insufficient to contain a spill. Previous corrective action was not completed.			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 603.o.			Date:

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713600772	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6440145