

Inspection Photos

API: 099-06248

Operator: MURFIN DRILLING COMPANY INC

Inspection Date: 2/21/2024

County: Prowers



Inspection Photos



Photo 1. Facing east toward the access road. The road needs to be regraded and decompacted.



Inspection Photos



Photo 2. Facing toward the abandoned wellsite. There is a flowline pipe that needs to be removed.



Inspection Photos



Photo 3. Facing northwest. The rock debris needs to be picked up and removed so it wont interfere with farming operations.



Inspection Photos



Photo 4. Facing back west at the abandoned location. Soils need to be decompacted by cross ripping to at least 18 inches.

