

Gadeco LLC
Hiawatha State 2-36
Location ID: 313297



As signs are replaced additional information will be required



Entrance to location



Gadeco LLC
Hiawatha State 2-36
Location ID: 313297



Debris



Debris

Gadeco LLC
Hiawatha State 2-36
Location ID: 313297



Debris



Debris

Gadeco LLC
Hiawatha State 2-36
Location ID: 313297



Equipment leaks and stained soil



Debris

Gadeco LLC
Hiawatha State 2-36
Location ID: 313297



Debris. No containment.



Unidentified contents. No containment.

Gadeco LLC
Hiawatha State 2-36
Location ID: 313297



Leaking equipment and stained soil



Sucker rod alongside unit

Gadeco LLC
Hiawatha State 2-36
Location ID: 313297



Debris



Debris

Gadeco LLC
Hiawatha State 2-36
Location ID: 313297



Debris



Debris

Gadeco LLC
Hiawatha State 2-36
Location ID: 313297



Debris



Tank labels missing required information

Gadeco LLC
Hiawatha State 2-36
Location ID: 313297



Oily waste and stained soil



Oily waste and stained soil

Gadeco LLC
Hiawatha State 2-36
Location ID: 313297



Tank labels missing required information



Tank labels missing required information

Gadeco LLC
Hiawatha State 2-36
Location ID: 313297



Tank labels missing required information



Debris. Oily waste.

Gadeco LLC
Hiawatha State 2-36
Location ID: 313297



Oily waste



Debris

Gadeco LLC
Hiawatha State 2-36
Location ID: 313297



Oily waste covering relief valves



Oily waste covering relief valves

Gadeco LLC
Hiawatha State 2-36
Location ID: 313297




Debris



Oily waste and stained soil

Gadeco LLC
Hiawatha State 2-36
Location ID: 313297



Debris



Unmarked anchor

Gadeco LLC
Hiawatha State 2-36
Location ID: 313297



Location from Northwest corner



Location from Northeast corner

Gadeco LLC
Hiawatha State 2-36
Location ID: 313297



Location from Southeast corner



Location from Southwest corner