

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/22/2024

Submitted Date:

02/25/2024

Document Number:

708903151**FIELD INSPECTION FORM**

Loc ID 311608	Inspector Name: Smelser, Wayne	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 25 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
------------------	-----------------------------------	---	-------------------	--

Operator Information:
 OGCC Operator Number: 10456
 Name of Operator: CAERUS PICEANCE LLC
 Address: 1001 17TH STREET #1600
 City: DENVER State: CO Zip: 80202

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:			
Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
266194	WELL	PR	11/08/2003	GW	045-09125	SCHAEFFER 12-6C (F12W)	PR
276406	WELL	PR	01/20/2006	GW	045-10454	SHAEFFER 12-3A (F12W)	PR
276407	WELL	PR	02/06/2006	GW	045-10453	SHAEFFER 12-12A (F12W)	PR

General Comment:

CECMC Inspection Report Summary
 On 02/22/2024 at approximately 11:25 hours, I, Compliance Specialist, Wayne Smelser
 Conducted an on-site inspection at CAERUS PICEANCE LLC SCHAEFFER 12-6C (F12W) Pad.
 Location # 311608 in Garfield County Colorado.
 Location is within High Priority/Density/Black Bear Habitat areas.
 While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Tanks & Berms - Multiple holes in containment liner/liner needs maintenance with a CA date of 03/16/2024

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.
 This is a summary of inspection report.

Dual Lease - shared pad & facilities with location # 334607

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Sign near entrance to location		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Chemical tank		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-2615

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Cattle panels		
Corrective Action:		Date:	

Equipment:				corrective date
Type: Vertical Heated Separator	# 5			
Comment:				
Corrective Action:				Date:
Type: Gas Meter Run	# 1			
Comment:	Summit Midstream			
Corrective Action:				Date:
Type: Plunger Lift	# 3			
Comment:	All wells on plunger lift			
Corrective Action:				Date:
Type: Ancillary equipment	# 1			
Comment:	Chemical tank			
Corrective Action:				Date:
Type: Other	# 1			
Comment:	Telemetry			
Corrective Action:				Date:
Type: Bradenhead	# 3			
Comment:	Pressure transducers located on all bradenhead. All bradenhead valves are accessible.			
Corrective Action:				Date:
Type: Gas Meter Run	# 5			
Comment:				
Corrective Action:				Date:
Type: Bird Protectors	# 2			
Comment:				
Corrective Action:				Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	500 BBLS	STEEL AST		,	
Comment:	Tank equipped with telemetry Centralized containment					
Corrective Action:					Date:	

Paint

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Inadequate	Walls Insufficient		Inadequate
Comment:	Multiple holes in secondary containment liner/liner needs maintenance			

Corrective Action:		The liner will be sufficiently impervious so that any discharge from a primary containment system will not escape containment before cleanup occurs.				Date:		03/16/2024	
Contents		#	Capacity	Type	Tank ID	SE GPS			
CONDENSATE		1	300 BBLs	STEEL AST		,			
Comment:		Tank equipped with telemetry							
		Centralized containment							
Corrective Action:						Date:			
<u>Paint</u>									
Condition		Adequate							
Other (Content)									
Other (Capacity)									
Other (Type)									
<u>Berms</u>									
Type	Capacity	Permeability (Wall)		Permeability (Base)		Maintenance			
Metal									
Comment:									
Corrective Action:						Date:			
<u>Venting:</u>									
Yes/No		NO							
Comment:									
Corrective Action:						Date:			
<u>Flaring:</u>									
Type									
Comment:									
Corrective Action:						Date:			

Inspected Facilities									
Facility ID:	266194	Type:	WELL	API Number:	045-09125	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	276406	Type:	WELL	API Number:	045-10454	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	276407	Type:	WELL	API Number:	045-10453	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						Sparse to none in areas
		Ditches				
				Material Handling And Spill Prevention		Chemical tank containment
		Tracking Pad				Aggregate/gravel based VTC
		Gravel				Sparse to none in areas
		Culverts				
Compaction						Light compaction
Berms						
		Compaction				Light compaction in sections

Comment: Location shows some signs of lack of stabilization/compaction in small areas.

Aggregate/gravel based VTC on lease road near entrance to location. Dimensions & details are as follows - approximately 78 ft long, 18 ft wide & varying depths from 1-3 inches, depth insufficient, area does not appear to have been excavated & no class 2 geotextile fabric observed. BMP is becoming compacted & sediment laden in some areas & may need maintenance in the near future.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Please refer to Tanks & Berms for observed compliance issue.	smelserw	02/25/2024
Dual Lease - shared pad & facilities with location # 334607		

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708903152	Inspection 708903151 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6442058
708903153	Inspection 708903151 Stormwater photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6442059