

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/15/2024

Submitted Date:

02/19/2024

Document Number:

708903098**FIELD INSPECTION FORM**Loc ID 334602 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

24 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
263849	WELL	PR	03/18/2005	GW	045-08146	CEDAR SPRINGS RANCH 11-11	PR
271508	WELL	PR	04/01/2005	GW	045-09892	CEDAR SPRINGS RANCH 11-7D(J11W)	PR
271940	WELL	PR	05/07/2013	GW	045-09980	CEDAR SPRINGS RANCH 11-11C (J11W)	PR
271941	WELL	PR	03/03/2005	GW	045-09981	CEDAR SPRINGS RANCH 11-10D (J11W)	PR
271967	WELL	PR	04/09/2005	GW	045-09978	CEDAR SPRINGS RANCH 11-11D (J11W)	PR

General Comment:**CECMC Inspection Report Summary**

On 02/15/2024 at approximately 12:14 hours, I, Compliance Specialist, Wayne Smelser

Conducted an on-site inspection at CAERUS PICEANCE LLC CEDAR SPRINGS RANCH 11-11 (J11W) Pad.

Location # 334602 in Garfield County Colorado.

Location is within High Priority/Density/Black Bear Habitat areas & in close proximity to NSO Habitat area.

Location is approximately 370 yards from Dry Creek.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Tanks & Berms - Hole in secondary containment liner/liner needs maintenance with a CA date of 03/10/2024

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection report.

Dual lease - shared facilities with location # 324074

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Sign at entrance to location		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:		
Comment:	911/970-285-2615	
Corrective Action:		Date: _____

Good Housekeeping:		
Type	DEBRIS	
Comment:	Debris - please refer to photo log	
Corrective Action:		Date:

Overall Good: ☐

Spills:			
Type	Area	Volume	
In Containment:	No		
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			

Fencing/:		
Type	OTHER	
Comment:	Summit Midstream meter house - bollards	

Corrective Action:		Date:	
Equipment:		corrective date	
Type: Vertical Heated Separator	# 4		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment: Summit Midstream			
Corrective Action:		Date:	
Type: Bradenhead	# 5		
Comment: Pressure transducers located on all bradenhead. All bradenhead valves are accessible.			
Corrective Action:		Date:	
Type: Gas Meter Run	# 6		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 5		
Comment: All wells on plunger lift			
Corrective Action:		Date:	
Type: Other	# 1		
Comment: Telemetry			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	1000 GAL	STEEL AST		,
Comment: Centralized containment					
Corrective Action:				Date:	

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal				
Comment:				

Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	OTHER	STEEL AST		,	
Comment: Centralized containment Tanks equipped with telemetry						
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	250 bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Inadequate	Walls Insufficient		Inadequate
Comment: Hole in secondary containment liner/liner needs maintenance				
Corrective Action: The liner will be sufficiently impervious so that any discharge from a primary containment system will not escape containment before cleanup occurs.				Date: 03/10/2024

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	263849	Type:	WELL	API Number:	045-08146	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	271508	Type:	WELL	API Number:	045-09892	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	271940	Type:	WELL	API Number:	045-09980	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	271941	Type:	WELL	API Number:	045-09981	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	271967	Type:	WELL	API Number:	045-09978	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
Compaction						Light compaction in some areas
		Culverts				
Gravel						Sparse to none in areas
		Compaction				Light compaction in some areas
		Gravel				Sparse to none
Berms						

Comment: [Places with sparse to no gravel & light compaction are present on location. Sparse/no gravel and light compaction could lead to future stabilization and tracking issues.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Please refer to Tanks & Berms for observed compliance issue.	smelserw	02/19/2024
Dual lease - shared facilities with location # 324074		

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403691861	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6434656
708903099	Inspection 708903098 Stormwater photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6434649
708903100	Inspection 708903098 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6434650