

Inspection Photos

Location Name: CAERUS PICEANCE LLC, FEDERAL-68S96W/13SWSW

Location ID: 334154

Date: 2/26/2024



Location Entrance – Photo #09543



Wellhead/Weeds – Photo #09546

Inspection Photos

Location Name: CAERUS PICEANCE LLC, FEDERAL-68S96W/13SWSW

Location ID: 334154

Date: 2/26/2024



Feb 26, 2024 at 16:25:18

Separator – Photo #09544



Feb 26, 2024 at 16:26:56

Tank Battery/No Battery Sign Posted – Photo #09547

Inspection Photos

Location Name: CAERUS PICEANCE LLC, FEDERAL-68S96W/13SWSW

Location ID: 334154

Date: 2/26/2024



Methanol Tank Tipped Against Condensate Tank/General Safety – Photo #09548



Methanol Tank Tipped Against Condensate Tank/General Safety – Photo #09549

Inspection Photos

Location Name: CAERUS PICEANCE LLC, FEDERAL-68S96W/13SWSW

Location ID: 334154

Date: 2/26/2024



Lack of Stabilization – Photo #09550



Lack of Stabilization – Photo #09551

Inspection Photos

Location Name: CAERUS PICEANCE LLC, FEDERAL-68S96W/13SWSW

Location ID: 334154

Date: 2/26/2024



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #09552**