

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/20/2024

Submitted Date:

02/20/2024

Document Number:

699108280

FIELD INSPECTION FORM

Loc ID 418799 Inspector Name: Burns, Adam On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 2001 16TH STREET SUITE 900
City: DENVER State: CO Zip: 80202

Findings:

- 7 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|---|---------------------------------|
| , | | rbucogccinspectionreports@chevron.onmicrosoft.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|--------------|--------|-------------|------------|---------|----------------------|-------------|
| 447380 | TANK BATTERY | AC | 08/19/2016 | | - | Coleman C22-18D Tank | AC |

General Comment:

[This is an inspection on the tank battery](#)

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|--|-------|------------|
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | OTHER | | |
| Comment: | Unmarked riser needs to be marked by identifying what they are and tagged with OOSLAT. "LOTO" See attached photo | | |
| Corrective Action: | Comply with the 1100 rules. | Date: | 03/01/2024 |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | | |
|--------------------|----------|-------|-------|
| Comment: | Adequate | | |
| Corrective Action: | | Date: | _____ |

Overall Good:

Spills:

| Type | Area | Volume | | |
|------|------|--------|--|--|
| | | | | |

In Containment: No

Comment: _____

Multiple Spills and Releases?

Equipment:

| Type | # | | corrective date |
|-----------------------------|--------|-------|-----------------|
| Horizontal Heated Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Emission Control Device | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Gas Meter Run | # 2 | | |
| Comment: | 1 shed | | |
| Corrective Action: | | Date: | |
| Bird Protectors | # 3 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-------------|---------|--------|
| PRODUCED WATER | 1 | OTHER | BV CONCRETE | | , |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |

| | |
|------------------|---------|
| Paint | |
| Condition | |
| Other (Content) | |
| Other (Capacity) | 48 BBLs |
| Other (Type) | |

| | | | | |
|--------------------|----------|---------------------|---------------------|-------------|
| Berms | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| | | | | |
| Comment: | | | | Date: |
| Corrective Action: | | | | Date: |

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-------------|---------|--------|
| PRODUCED WATER | 3 | OTHER | BV CONCRETE | | |
| Comment: | | | | | Date: |
| Corrective Action: | | | | | Date: |

| | |
|------------------|---------|
| Paint | |
| Condition | |
| Other (Content) | |
| Other (Capacity) | 60 BBLs |
| Other (Type) | |

| | | | | |
|--------------------|----------|---------------------|---------------------|-------------|
| Berms | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| | | | | |
| Comment: | | | | Date: |
| Corrective Action: | | | | Date: |

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|-----------------------|
| CRUDE OIL | 4 | 300 BBLs | STEEL AST | | 40.304800,-104.533900 |
| Comment: | | | | | Date: |
| Corrective Action: | | | | | Date: |

| | |
|------------------|----------|
| Paint | |
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

| | | | | |
|--------------------|----------|---------------------|---------------------|-------------|
| Berms | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Metal | Adequate | Walls Sufficent | Base Sufficient | Adequate |
| Comment: | | | | Date: |
| Corrective Action: | | | | Date: |

| | |
|-----------------|----|
| Venting: | |
| Yes/No | NO |

| | | | |
|--------------------|--|-------|--|
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | | |
|--------------------|--|-------|--|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected Facilities

Facility ID: 447380 Type: TANK API Number: - Status: AC Insp. Status: AC

Producing Well

Comment: active tank battery

Corrective Action:

Date:

COGCC Comments

| Comment | User | Date |
|---|--------|------------|
| <p>ECMC Inspection Report Summary On Tuesday 2/20/24 at approximately 0953hrs I, Inspector Adam Burns, Conducted an on-site inspection at Coleman C22-18D Tank Battery of Chevron. Location ID: 447380 in Weld County, Colorado. During this inspection the following possible compliance issues were observed: Unmarked riser needs to be marked by identifying what they are and tagged with OOSLAT. "LOTO" Comply with the 1100 rules. With a Corrective Action date of 3/1/24 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules. This is a summary of the inspection report.</p> | burnsa | 02/20/2024 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 403692599 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6435475 |
| 699108281 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6435473 |