

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/26/2024

Submitted Date:

02/27/2024

Document Number:

693701125

FIELD INSPECTION FORM

Loc ID: 307072 Inspector Name: ALLISON, RICK On-Site Inspection: 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 95233
Name of Operator: WELLINGTON OPERATING COMPANY
Address: 15301 DALLAS PKWY SUITE 900
City: ADDISON State: TX Zip: 75001

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 5 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Randy Evans		rgrevans477@gmail.com	Wellington Operating
Sydney McLeod		mcleodsg@co.larimer.co.us	Larimer County
James Young		jayyoung@kingoperating.com	Wellington Operating Principal Agent
Gracey, Cam		graceyservices@msn.com	
Wheeler, Steven		steven.wheeler@state.co.us	ECMC Integrity Engineer

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216745	WELL	PA	04/24/2023	OW	069-05168	WELLINGTON MUDDY UNIT/GAULT-PIATT 20-3	EI
486151	SPILL OR RELEASE	AC			-	WELLINGTON MUD U/GAULT-PIATT #20-3	EI

General Comment:

Inspected Facilities

Facility ID: 216745 Type: WELL API Number: 069-05168 Status: PA Insp. Status: EI

Facility ID: 486151 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Environmental

Spill/Remediation:

Comment: [ECMC Environmental Inspection of remediation of historical impacts discovered at well during plugging and abandonment. Reported as Spill ID 486151 with remediation reporting under Remediation Project 28548.](#)

[Operator had stockpiled several hundred yards of impacted material on location and was preparing to haul to Pawnee Waste for disposal. ECMC observed the excavation around the well. No groundwater was observed. Operator has excavated into bedrock. Operator stated that confirmation soil samples had been collected and results are anticipated within 1 week.](#)

[Flowline is exposed in southeast corner of excavation. Operator indicated intention to abandon in place and flowline had been cut/capped at junction with trunkline with soil samples collected for analysis of Table 915-1 contaminants of concern. Operator will submit Form 44 for flowline abandonment in place with documentation required by Rule 1105.e. and 1105.f. \(2\)D.](#)

[Spill ID may be closed with reference to Remediation Project 28548 once updated Supplemental Form 27 with analytical results and remediation plans and implementation schedule are submitted and approved.](#)

Corrective Action: Date:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693701126	Excavation at well looking southeast	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6444418
693701127	Excavation at well looking southwest	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6444419