

Inspection Photos
Location Name: State 44-36
Location ID:306091



Energy & Carbon Management Commission
40.26571, -104.94808, 1495.3m, 131°
02/27/2024 11:49:20

Production facility




Energy & Carbon Management Commission
40.26445, -104.94483, 1492.0m, 44°
02/27/2024 11:51:13

Wellhead

Inspection Photos
Location Name: State 44-36
Location ID:306091



Calibration card on 12/13/2023



Calibration card on 2/27/2024