

Inspection Photos

API: 061-06394

Operator: STRACHAN EXPLORATION INC

Inspection Date: 2/27/2024



Inspection Photos



Photo 1. Facing southwest toward the offsite tank battery location. The unused tank has been removed.



Inspection Photos



Photo 2. The fence around the tank has been repaired. The wires are tight however there are only 2 wires which may not keep livestock out.



Inspection Photos



Photo 3. Facing south toward the tank battery. The secondary containment has been repaired.



Inspection Photos



Photo 4. Facing southwest at the meter shed. This pile of soil contains impacted soils with a hydrocarbon odor. This pile needs to be properly disposed.



Inspection Photos



Photo 5. Facing northwest toward the wellsite. The fence around the pumpjack is in disrepair and won't prevent livestock entry.



Inspection Photos



Photo 6. There is oily fluid in the containment next to the pump jack. Oily fluid has spilled onto the ground and needs to be cleaned up. Previous corrective action was not completed. Netting must be installed to prevent wildlife entry.

