

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/27/2024

Submitted Date:

02/28/2024

Document Number:

713600785

FIELD INSPECTION FORM

Loc ID 324837 Inspector Name: COSTA, RYAN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 83130
Name of Operator: STRACHAN EXPLORATION INC
Address: 992 S 4TH AVE SUITE 100-461
City: BRIGHTON State: CO Zip: 80601

Findings:

- 7 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
BEAR STACY		stacy@strachanexploration.co	
Harms, Jason		Jason@strachanexploration.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
324837	LOCATION	AC			-	STAVELY-618S51W 26SESE	RI

General Comment:

This is a follow up of the previous inspection #713600434.
See attached photos and additional details within this report

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	There is oily fluid that has overtopped the containment and spilled out by the pumpjack. Previous corrective action has not been completed.		
Corrective Action:	Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 906. Immediate clean up. Implement or modify BMPs for improved material handling and spill prevention.		Date: <u>06/29/2023</u>
Type	UNUSED EQUIPMENT		
Comment:	The unused tank and pipe have been removed.		
Corrective Action:			Date:

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	PUMP JACK		
Comment:	The fence around the pump jack is inadequate to prevent livestock entry and is not maintained.		
Corrective Action:	Comply with the fencing requirements per the 1002a rules		Date: <u>03/15/2024</u>
Type	TANK BATTERY		
Comment:	The fence at the tank battery has been repaired. The wires are tightened however the 2 wires will likely not keep livestock out.		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
	3				
Comment:					
Corrective Action:					Date:

Paint

Condition	<input type="text"/>
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Earth	Adequate			Adequate	
Comment:	The berm at the tank battery has been built up for secondary containment.				
Corrective Action:				Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Environmental

Waste Management:

Type	Management	Condition	GPS (Lat)	(Long)
Oily Soil	Piles	Inadequate		
Comment	There is a pile of impacted soil excavated from the tank battery which has been placed on the ground next to the meter shed. E&P Waste are not properly stored, handled, transported, treated, recycled, or disposed per Rule 905.			
Corrective Action	Properly dispose of oily waste in accordance with Rule 905.e			Date: 03/01/2024

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713600786	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6447361