

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/26/2024

Submitted Date:

02/28/2024

Document Number:

707602452**FIELD INSPECTION FORM**Loc ID 322987 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		dnr_cogccengineering@state.co.us	
,		cogccinspection@pdce.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
244587	WELL	PR	01/01/2021	GW	123-12382	EHRlich 1	PA

General Comment:

This is a **PLUGGED & ABANDONED WELL / WORKOVER** inspection.

Well(s): 1: Plugged & Abandoned | PA.

Plugging Operations: Workover; Cut & pull casing.

Battery: Inactive. Shut-down.

Inactive Battery SE corner GPS coordinates: 40.497670 / -104.595790

Well GPS coordinates: 40.498860 / -104.599690

Location**Lease Road:**

Type	Access		
comment:	Adequate		
Corrective Action:		Date:	

Overall Good: ☐**Signs/Marker:**

Type	OTHER		
Comment:	Jobsite entrance & safety signage posted.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Plunger Lift	# 0		corrective date
Comment:	Plugged & Abandoned PA. Equipment removed.		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	244587	Type:	WELL	API Number:	123-12382	Status:	PR	Insp. Status:	PA
Workover									
Comment:	<p>2024/02/26: Plugging Operations: Workover; Cut & pull casing. 2024/02/26: JSA attached as photo to this report. Workover Contractor: Ensign Energy Services Rig #314. Cement Contractor: Duco Services.</p> <p>Reference: Form 6N on file. Notice of Intent to Abandon date: 02/02/2024. Approved. Form 42 on file. Notice of MIRU. Start Date: 02/19/2024. Approved. Form 42 on file. Notice of Plugging Operations. Start Date: 02/19/2024. Approved. Form 17 Brhd test on file. Date: 02/19/2024.</p> <p>CREW TRAVEL. PRE JOB SAFETY MEETING AND JSA. CHECK PRESSURES. SICP 0PSI. SIBHP 24PSI. TIE IN PUMP LINES. OPEN UP SURFACE TO WORK TANK. BLED OFF INSTANTLY. FUNCTION TEST BOP. TEST GOOD. MIRU SUREFIRE WIRELINE. HELD SAFETY MEETING. PU RIH WITH 4.5" JET CUTTER. CORRELATE WITH LOG. CUT CASING @ 2480'. GOOD CUT. RDMO SUREFIRE WIRELINE. TIE IN PUMP LINES. PUMP DOWN CASING THROUGH CUT @ 2480'-SURFACE ANNULAS. CIRCULATED WELL FOR 4 HOURS CLEAN OF ALL OIL, GAS AND HEAVY MUD. 15 MINUTE FLOW CHECK. TEST GOOD. ND BOP AND LARKIN ADAPTER FLANGE. REMOVE 3K WELL HEAD AND SURFACE CAP. UNLAND CASING. STRIP OVER LARKIN ADAPTER FLANGE, WORK SPOOL AND BOP. RU WORK FLOOR AND HANDLING EQUIPMENT. LD 60 AND A PARTCIAL OF 4.5" 11.6# CASING. SHUT AND SECURE WELL. CREW CLEANED LOCATION AND WINTERIZED EQUIPMENT.</p>								
Corrective Action:								Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass			Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date:

Pits:

☐ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>CECMC Inspection Report Synopsis:</p> <p>On MON 02/26/2024 at approximately 12:29 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: PDC ENERGY INC Location Name: EHRlich-66N64W/7NWSW Location ID: 322987 Well Name(s): Ehrlich #1. API: 123-12382. Location County: Weld County, Colorado Weather: Mostly Sunny, Windy, damp from prior storm.</p> <p>While there, I observed: Well(s): 1: Plugged & Abandoned PA. Plugging Operations: Workover; Cut & pull casing. Battery: Inactive. Shut-down. Inactive Battery SE corner GPS coordinates: 40.497670 / -104.595790 Well GPS coordinates: 40.498860 / -104.599690</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	02/28/2024

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707602454	Site photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6447716