

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/28/2024

Submitted Date:

02/28/2024

Document Number:

702403162**FIELD INSPECTION FORM**Loc ID 317668 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

20 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rwatzman@kpk.com	All Inspections
,		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
239747	WELL	PR	12/01/2019	OW	123-07535	SUCKLA FARMS INC E 1	PR
448242	TANK BATTERY	AC	11/01/2016		-	SUCKLA FARMS E BATTERY	AC

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	stained soil & debris by the tank battery flow line by the west tank and center tank.		
Corrective Action:	Properly dispose of oily waste in accordance with 905.e.	Date:	03/14/2024

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	Ancillary equip. has fabricated steel pipe.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Gas Meter Run has Ag panel		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	barb wire		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	barb wire		
Corrective Action:		Date:	
Type	PUMP JACK		

Comment:	hog fence		
Corrective Action:		Date:	
Type	OTHER		
Comment:	flow line manifold has barb wire		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	barb wire		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	automation, Electric panel, meter box and transformers		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	no indication of calibration status		
Corrective Action:	Comply with Rule 430	Date:	03/28/2024
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	flow line manifold		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	300 BBLS	STEEL AST		,	
Comment:						
Corrective Action:					Date:	

Paint

Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate

Comment:		shares containment with crude tanks						
Corrective Action:							Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS			
CRUDE OIL	2	300 BBLs	STEEL AST		40.095570,-104.884110			
Comment:								
Corrective Action:							Date:	
<u>Paint</u>								
Condition	Adequate							
Other (Content)								
Other (Capacity)								
Other (Type)								
<u>Berms</u>								
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance				
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate				
Comment:								
Corrective Action:							Date:	
<u>Wells Served By Facilities Above</u>								
<u>AirsID</u>								
API Number			API Number		AirsID			
123-07548								
123-07535								
123-08887								
<u>Venting:</u>								
Yes/No	NO							
Comment:								
Corrective Action:						Date:		
<u>Flaring:</u>								
Type								
Comment:								
Corrective Action:						Date:		

Inspected Facilities									
Facility ID:	239747	Type:	WELL	API Number:	123-07535	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR, Electric panel and meter box are shut off								
Corrective Action:								Date:	
BradenHead									
Date of Last Brhd Test:	03/28/2023		Annual Brhd Completed?		Yes				
Last Brhd Test Results	Initial Surf Csg Pressure:		0		Fluid Type:				
	End Surf Csg Pressure:		0						
Comment:	plumbed to surface								
Corrective Action:								Date:	
Facility ID:	448242	Type:	TANK	API Number:	-	Status:	AC	Insp. Status:	AC

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Comment: <input type="text"/>						Date: <input type="text"/>
Corrective Action: <input type="text"/>						
Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						

COGCC Comments

Comment	User	Date
ECMC Inspection Report Summary On Wednesday 2-28-2024 at approximately 1300 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection: Operator: KP Kauffman Location name: Location ID #317668 Well Name: Suckla Farms Inc. E 1 API # 05-123-07535 County: Weld Weather: Clear Location: Dry While there, I observed a wellsite & tank battery, PR at the time of the inspection, electric panel is shut off. During this inspection, I observed the following possible compliance issues: 905.e Housekeepng: CA date 3-14-2024. 430 Meter calibration: CA date 3-28-2024. See attached photos. A follow up site inspection is needed to ensure that the addressed Compliance issues comply with ECMC rules.	revasr	02/28/2024

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702403163	location photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6447826