

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/28/2024

Submitted Date:

02/28/2024

Document Number:

713300643

FIELD INSPECTION FORM

Loc ID 317736 Inspector Name: Kester, Michael On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Findings:

8 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|---------------|--------------|--------------------------|---------------------------------|
| , KPK | 303-825-4822 | cogcc@kpk.com | all inspections |
| Silver, Randy | 720-827-6688 | randy.silver@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 239890 | WELL | PR | 06/01/2023 | OW | 123-07678 | CARL M CARY 1 | PR |

General Comment:

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|------------|-------|--|
| Type | WELLHEAD | | |
| Comment: | Very FADED | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | | |
|--------------------|--|-------|--|
| Comment: | | Date: | |
| Corrective Action: | | | |

Overall Good:

Spills:

| Type | Area | Volume | | |
|------|------|--------|--|--|
| | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

| | | | |
|--------------------|---------------|-------|--|
| Type | PUMP JACK | | |
| Comment: | safety guards | | |
| Corrective Action: | | Date: | |

Equipment:

| Type | Area | Volume | corrective date |
|---------------------------|-----------------------------|--------|-----------------|
| Type: Prime Mover | | # 1 | |
| Comment: | electric motor | | |
| Corrective Action: | | Date: | |
| Type: Pump Jack | | # 1 | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | | # 1 | |
| Comment: | electrical disconnect panel | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | | # 1 | |
| Comment: | piped to surface | | |
| Corrective Action: | | Date: | |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|----------|--|--|
| Type | | |
| Comment: | | |

Corrective Action:

Date:

Inspected Facilities

Facility ID: 239890 Type: WELL API Number: 123-07678 Status: PR Insp. Status: PR

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: Valves appeared to be closed at time of inspection

Corrective Action:

Date:

COGCC Comments

| Comment | User | Date |
|--|---------|------------|
| <u>Follow up inspection as per Doc # 713300271, corrective actions appeared to have been addressed</u> | kesterm | 02/28/2024 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 713300644 | site pic | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6448300 |