

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/29/2024

Submitted Date:

02/29/2024

Document Number:

698601575

FIELD INSPECTION FORMLoc ID 304952 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10699

Name of Operator: OWN RESOURCES OPERATING LLC

Address: 305 S RIDGE STREET #6279

City: BRECKENRIDGE State: CO Zip: 80424

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

19 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Dolezal, Pat	970-332-3585	pat.dolezal@ownresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
277059	WELL	PR	01/01/2022	GW	125-09192	FONTE 33-21	PR

General Comment:

Routine inspection and Rig inspection. Operator is attempting casing repair.

Location

Lease Road:			
Type	Access		
comment:	Two track off maintained County Road. Active agricultural cropland with seasonal access to well location.		
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	OTHER		
Comment:	Well sign posted at CR and access intersection.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Well sign located at wellhead.		
Corrective Action:		Date:	
Type	DRILLING/RECOMP		
Comment:	Rig sign posted at CR and access intersection.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Emergency contact information posted on well signs.

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Stock panel fencing around surface equipment at well location.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Dehydrator	# 1		
Comment:	Dehydrator on gas meter run inlet.		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Horsehead currently removed to facilitate well work.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Pump Jack Power and Control Panel.		
Corrective Action:		Date:	

Type: Ancillary equipment	# 1		
Comment:	Wellhead. Rods and tubing in the wellbore. Tubing valve closed. Casing valve closed.		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Bradenhead plumbed to surface.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Flowline mounted metal meter box.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:	Located 4 marked anchors.		
Corrective Action:		Date:	
Type: Gas Meter Run	#		
Comment:	Digital Gas Meter Run. Meter Calibration/Test Log dated 8-24-23. Well Inlet Valve open. Gas Outlet Valve open.		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric Motor.		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	277059	Type:	WELL	API Number:	125-09192	Status:	PR	Insp. Status:	PR
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder:									
Comment: Well is currently SI for workover and casing repair.									
Corrective Action: Date:									
Workover									
Comment: Excell Services LLC, Workover Rig #5 is currently rigged up on well. Operator has identified suspected leak in casing and will attempt to repair casing. If it cannot be repaired they will plug and abandon. Pump Jack Horsehead removed. Rods have been removed from wellbore. Crew is hydro testing tubing to ensure string is good for use. Service Rig sign at CR intersection. Rig floor and walkway safety barriers and equipment in use. Personal PPE in use. Repair Plan: Run in scraper to clean up wellbore. Set CICR above production perfs. Circulate and load wellbore. Pressure test wellbore. Run CBL. Run in Packer and locate hole. Perf casing and set CICR. Cement casing string to surface. Pressure test wellbore. Determine next steps based on repair outcome.									
Corrective Action: Date:									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No stormwater issues noted at time of inspection.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698601679	Inspection photos.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6448633