

Interim Reclamation and Stormwater Inspection

Date: 2/22/24

Operator: Highpoint Operating Corporation - 10071

Location ID: 443153

Inspection Document #: 713900406

Weld County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location Name: Anschutz Equus Farms

4-62-9_10 South

Location ID: 443153



Photo 1. The photo was taken at the well location entrance facing Southeast. The photo illustrates the access road and an overview of the facility.

Photo 2. The photo was taken at the well location entrance facing East. The photo illustrates the interim area has been mowed on the North side of the facility.

Inspection Photos

Location Name: Anschutz Equus Farms

4-62-9_10 South

Location ID: 443153



ECMC
140° SE
2/22/24, 3:25 PM



ECMC
333° NW
2/22/24, 3:26 PM

Photo 3. The photo was taken at the well location entrance facing Southeast. The photo illustrates the interim area has been mowed on the West side of the facility.

Photo 4. The photo was taken at the well location facing Northwest. The photo illustrates the tank is missing a tank placard.

Inspection Photos

Location Name: Anschutz Equus Farms

4-62-9_10 South

Location ID: 443153



Photo 5. The photo was taken at the well location facing Northwest. The photo illustrates the active excavation of a reported spill on the facility production pad.

Note - The excavation was fenced in and not being worked on during the inspection.

Inspection Photos

Location Name: Anschutz Equus Farms

4-62-9_10 South

Location ID: 443153



Photo 6. The photo was taken at the well location facing East. The photo illustrates the interim area has been mowed on the Southeast side of the facility.



Photo 7. The photo was taken at the well location facing North. The photo illustrates the interim area has been mowed on the East side of the facility.

Inspection Photos

Location Name: Anschutz Equus Farms

4-62-9_10 South

Location ID: 443153



Photo 8. The photo was taken at the well location facing Northwest. The photo illustrates the interim area has been mowed on the Northeast side of the facility.

Photo 9. The photo was taken at the well location facing South. The photo illustrates the the berm around the production pad.