

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/28/2024

Submitted Date:

02/29/2024

Document Number:

705000638

FIELD INSPECTION FORM

Loc ID 332894 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

- 2 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		ECMCInspections@Oxy.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
250938	WELL	SI	11/01/2023	GW	123-18741	HSR-SEKICH 3-19A	PA
330913	LOCATION	AC			-	HSR-GRANDVIEW ESTATES-63N67W 19SENW	EG

General Comment:

[ECMC Engineering Integrity Inspection; Flowline Inspection](#)
[Photos uploaded](#)

Inspected Facilities

Facility ID: 250938 Type: WELL API Number: 123-18741 Status: SI Insp. Status: PA

Flowline

#1	Type: Non-Well Site	of Lines
----	---------------------	----------

Flowline Description

Flowline Type: Non-Well Site Size: 2" Material: Carbon Steel
 Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: Well is plugged and abandoned (HSR Sekich 3-19A); ECMC form 42 notice of start of plugging operations doc #403552932 received on 10/06/2023. The facility/ tank battery has been decommissioned (ID #318771); tanks and equipment removed. On location dump and process flowlines at facility/ battery are removed; ECMC form 42 notice of flowline abandonment completed doc #403669558 received 01/29/2024. No flowlines/ risers observed. Fenced excavations observed at PA well and facility/ battery areas. Excavation/ remediation work is in progress.

Corrective Action:

Date:

Facility ID: 330913 Type: LOCATION API Number: - Status: AC Insp. Status: EG

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
705000640	Signage at PA well	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6449179
705000641	View from PA well to decommissioned battery; to SW	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6449180