

Inspection Photos

2/27/2024

Operator: CAERUS PICEANCE LLC #10456

Location ID: 335781

Inspection Doc: 696205628

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335781



Photo 1: Photos 1-2 taken from the north end of the Location. Photos provide an overview of the Location from east, southeast, southwest to west. Photos also examples showing additional work to stabilize the upper areas of the Location appear to have been performed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335781



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335781



February 27, 2024

Photo 3: Photo examples showing caps/plugs have been installed at the lines at tanks.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335781



Photo 4: Photos taken from the western working pad surface. BMPs to stabilize the working pad surface appears to have been maintained; additional compaction is apparent, and potentially addition of road base material. Continue to monitor and maintain BMPs to ensure location remains stabilized.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335781



Photo 5: Photos taken from the east end of the upper working pad surface, facing east and southeast. Photo shows stormwater remains ponding on the lower working pad surface has persisted. This has resulted in stormwater contact with production equipment (wells). Ponding has also contributed to the stabilizing and tracking issues observed on the lower working pad surface.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335781



Photo 6: Photo taken from the lower working pad surface on the east end of the Location. Photos show BMPs to stabilize the working pad, as well as to minimize tracking, degradation and sediment transport remain missing or insufficient.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335781



February 27, 2024

Photo 7: Photo taken from the wells on the east end of the Location. Photo shows stormwater ponding around the well equipment.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335781



Photo 8: Photo taken from the Location entrance. Photo shows the vehicle tracking pad has not been maintained, and remains filled with sediment.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources