

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/30/2024

Submitted Date:

03/01/2024

Document Number:

698601589

FIELD INSPECTION FORMLoc ID 304452 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10699

Name of Operator: OWN RESOURCES OPERATING LLC

Address: 305 S RIDGE STREET #6279

City: BRECKENRIDGE State: CO Zip: 80424

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

16 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Dolezal, Pat	970-332-3585	pat.dolezal@ownresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
262504	WELL	PR	05/31/2007	GW	125-08461	GODSEY 43-20	PR

General Comment:

Routine inspection.

Location				
Lease Road:				
Type	Access			
comment:	Two track off maintained County Road.			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	Well sign located at wellhead.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	Emergency contact information posted on well sign.			
Corrective Action:				Date: _____
Good Housekeeping:				
Type	OTHER			
Comment:	Soil staining noted around Wellhead.			
Corrective Action:				Date:
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	WELLHEAD			
Comment:	Stock panel fencing around surface equipment at well location.			
Corrective Action:				Date:
Equipment:				
				corrective date
Type: Bradenhead	# 1			
Comment:	Bradenhead plumbed to surface.			
Corrective Action:				Date:
Type: Ancillary equipment	# 1			
Comment:	Pump Jack Power and Control Panel.			
Corrective Action:				Date:
Type: Ancillary equipment	# 1			
Comment:	Wellhead. Rods and tubing in the wellbore. Tubing valve open. Casing valve open.			
Corrective Action:				Date:
Type: Gas Meter Run	# 1			
Comment:	Digital Gas Meter Run. Meter Calibration/Test Log dated 8-7-23. Well Inlet Valve open. Gas Outlet Valve open.			

Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Separator/Meter Run Box.		
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:	Riser with plug at wellhead.		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric Motor.		
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 0		
Comment:	Could not locate any anchors at time of inspection.		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	262504	Type:	WELL	API Number:	125-08461	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Rods and tubing in wellbore. Tubing valve open. Casing valve open. Gas Meter Run Valves: Well inlet valve open, Gas outlet valve open. Electronic Well File reflects last Production/Status reported 12/1/2023 and Well Status as PR. Based on current valve settings at time of inspection the well is PR.								
Corrective Action:								Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Soil channel erosion channel off NE corner od wellhead fencing on access road. Channel flow is approximately 35'long down the grade with sediment fanwhere grade levels.

Corrective Action: Repair erosion damage and install appropriate BMP's to prevent reoccurrence. Review Self-inspection, maintenance, and good housekeeping procedures and schedules to facilitate identification of conditions that could cause breakdowns or failures of BMPs to comply with Rule 1002.(2).D.

Date: 03/11/2024

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698601693	Inspection photos.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6450395