

Inspection Photos

Location Name: CAERUS PICEANCE LLC Warren 15-9 (PI15) Pad

Location #: 334751



Photo # 8072 From entrance to location




Photo # 8073 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC Warren 15-9 (PI15) Pad

Location #: 334751



Photo # 8074 Location



Photo # 8075 Location



Inspection Photos

Location Name: CAERUS PICEANCE LLC Warren 15-9 (PI15) Pad

Location #: 334751



Photo # 8076 Location



Photo # 8077 Location



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location Name: CAERUS PICEANCE LLC Warren 15-9 (PI15) Pad

Location #: 334751



Photo # 8078 Location



Photo # 8079 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC Warren 15-9 (PI15) Pad

Location #: 334751



Photo # 8080 Valve on production tank leaking fluid



Photo # 8081 Valve on production tank leaking fluid

Inspection Photos

Location Name: CAERUS PICEANCE LLC Warren 15-9 (PI15) Pad

Location #: 334751



Photo # 8082 Debris



Photo # 8083 Debris

Inspection Photos

Location Name: CAERUS PICEANCE LLC Warren 15-9 (PI15) Pad

Location #: 334751



Photo # 8084 Debris