

Inspection Photos

Location Name: TEP Rocky Mountain LLC WATSON RANCH A Pad

Location # 413055



Photo # 8148 From entrance to location



Photo # 8149 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC WATSON RANCH A Pad

Location # 413055



Photo # 8150 Location



Photo # 8151 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC WATSON RANCH A Pad

Location # 413055



Photo # 8152 Location



Photo # 8153 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC WATSON RANCH A Pad

Location # 413055




Photo # 8154 Open ended pipes on production separators/wildlife hazards

Photo # 8155 Open ended pipe on production separator/wildlife hazard

Inspection Photos

Location Name: TEP Rocky Mountain LLC WATSON RANCH A Pad

Location # 413055



Photo # 8156 Wildlife egress on BAT 14B-17-07-95 well cellar not installed properly



Photo # 8157 Debris

Inspection Photos

Location Name: TEP Rocky Mountain LLC WATSON RANCH A Pad

Location # 413055



Photo # 8158 Debris

Photo # 8159 Debris

Inspection Photos

Location Name: TEP Rocky Mountain LLC WATSON RANCH A Pad

Location # 413055



Photo # 8160 Debris