

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/01/2024

Submitted Date:

03/02/2024

Document Number:

708903191

FIELD INSPECTION FORM

Loc ID 413055 Inspector Name: Smelser, Wayne On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Findings:

- 35 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
413086	WELL	PR	09/17/2010	GW	045-18713	BAT 22D-17-07-95	PR
413087	WELL	PR	10/18/2009	GW	045-18714	BAT 23D17-07-95	PR
413088	WELL	PR	08/01/2022	GW	045-18715	BAT 24B-17-07-95	PR
415492	WELL	PR	07/17/2010	GW	045-19066	BAT 34D-17-07-95	PR
415494	WELL	PR	07/19/2010	GW	045-19067	BAT 14D-17-07-95	PR
415528	WELL	PR	07/18/2010	GW	045-19082	BAT 24D-17-07-95	PR
415545	WELL	PR	01/01/2019	GW	045-19089	BAT 44A-18-07-95	PR
415560	WELL	PR	07/26/2010	GW	045-19095	BAT 23B-17-07-95	PR
415570	WELL	PR	05/21/2011	GW	045-19098	BAT 13D-17-07-95	PR
415573	WELL	PR	09/17/2010	GW	045-19101	BAT 34B-17-07-95	PR
415587	WELL	PR	07/23/2010	GW	045-19108	BAT 13B-17-07-95	PR
415590	WELL	PR	07/18/2010	GW	045-19109	BAT 14B-17-07-95	PR

General Comment:

CECMC Inspection Report Summary

On 03/01/2024 at approximately 13:41 hours, I, Compliance Specialist, Wayne Smelser
Conducted a follow up inspection at TEP ROCKY MOUNTAIN LLC WATSON RANCH A Pad.
Location # 413055 in Garfield County Colorado.

Please refer to inspection 708902653 conducted on 12/27/2023, previous corrective action has been completed.
Location is within High Priority/Density/Black Bear Habitat areas & in close proximity to NSO Habitat area.
Location is within Rule 411a Surface Water Internal Buffer.
While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Housekeeping - Wildlife egress on BAT 14B-17-07-95 well cellar not installed properly with a CA date of 03/09/2024
2. Equipment - Multiple open ended pipes on production separators/wildlife hazards with a CA date of 03/09/2024

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	CONTAINERS		
Comment:	Chemical tanks		
Corrective Action:			Date:
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	911/970-285-9377		
Corrective Action:			Date: _____

Good Housekeeping:			
Type	OTHER		
Comment:	Wildlife egress on BAT 14B-17-07-95 well cellar not installed properly		
Corrective Action:	Comply with CECMC wildlife rules		Date: 03/09/2024
Type	DEBRIS		
Comment:	Debris - please refer to photo log		
Corrective Action:			Date:

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No _____

Comment: _____

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Cattle panels		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	6ft security fencing		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Wire fence on west side of location showing some signs of disrepair.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 12		
Comment:	Taylor plugs located on all bradenhead. All bradenhead valves are accessible.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Telemetry		
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	# 4		
Comment:	Multiple open ended pipes on production separators/wildlife hazards		
Corrective Action:	Comply with CECMC wildlife rules	Date:	03/09/2024
Type: Gas Meter Run	# 12		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 6		
Comment:	Marked		
Corrective Action:		Date:	
Type: Bird Protectors	# 6		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Chemical tanks		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 12		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 12		
Comment:	All wells on plunger lift		

Corrective Action:	Date:
--------------------	-------

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		

Comment: Tank equipped with telemetry

Corrective Action:	Date:
--------------------	-------

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient		

Comment: Centralized containment

Corrective Action:	Date:
--------------------	-------

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		

Comment: Tank equipped with telemetry

Corrective Action:	Date:
--------------------	-------

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient		

Comment: Centralized containment

Corrective Action:	Date:
--------------------	-------

Venting:

Yes/No	NO			
Comment:				
Corrective Action:				Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	413086	Type:	WELL	API Number:	045-18713	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:					Date:				
Facility ID:	413087	Type:	WELL	API Number:	045-18714	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:					Date:				
Facility ID:	413088	Type:	WELL	API Number:	045-18715	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:					Date:				
Facility ID:	415492	Type:	WELL	API Number:	045-19066	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:					Date:				
Facility ID:	415494	Type:	WELL	API Number:	045-19067	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:					Date:				
Facility ID:	415528	Type:	WELL	API Number:	045-19082	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:					Date:				
Facility ID:	415545	Type:	WELL	API Number:	045-19089	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:					Date:				
Facility ID:	415560	Type:	WELL	API Number:	045-19095	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:					Date:				

Facility ID: <u>415570</u>	Type: <u>WELL</u>	API Number: <u>045-19098</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<u>Producing Well</u>				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
Facility ID: <u>415573</u>	Type: <u>WELL</u>	API Number: <u>045-19101</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<u>Producing Well</u>				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
Facility ID: <u>415587</u>	Type: <u>WELL</u>	API Number: <u>045-19108</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<u>Producing Well</u>				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
Facility ID: <u>415590</u>	Type: <u>WELL</u>	API Number: <u>045-19109</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<u>Producing Well</u>				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention		Chemical tank containments
		Culverts				
		Compaction				
Rip Rap						
		Ditches				
Compaction						
Check Dams						
		Gravel				Sparse
Gravel						Sparse in some areas

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Please refer to Housekeeping & Equipment for observed compliance issues.	smelserw	03/02/2024

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708903192	Inspection 708903191 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6451482
708903193	Inspection 708903191 Stormwater photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6451483