

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/02/2024

Submitted Date:

02/26/2024

Document Number:

697602267**FIELD INSPECTION FORM**Loc ID 335715 Inspector Name: Ahmadian, Alexander On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1700 LINCOLN ST STE 4550City: DENVER State: CO Zip: 80203**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Watzman, Ross	(303) 825-4822	rwatzman@kpk.com	all inspections.
Graber, Nikki		nikki.graber@state.co.us	
Peterson, John		jpeterson@kpk.com	KPK environmental
Brown, Kari		kari.oakman@state.co.us	
Anderson, Laurel		laurel.anderson@state.co.us	
, KPK		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201737	WELL	PR	02/01/2023	OW	001-07141	ZARLENGO 2	EI
478681	OFF-LOCATION FLOWLINE	AC	12/02/2020		-	Wellhead Line 4NWSW	EI

General Comment:

ECMC environmental inspection to determine progress on Spill ID 485983 Zarlengo #2 Flowline. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Representatives from Adams County and another Operator were onsite at the time of the inspection in order to document the spill and to observe the spill in relation with another flowline. Photos attached to document site conditions.

Location

Overall Good: ☐

Emergency Contact Number:

Comment: No signage at the spill

Corrective Action:

Date:

Overall Good: ☐

Spills:

Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:

Type	OTHER		
Comment:	Orange fencing around the excavation is adequate		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	201737	Type:	WELL	API Number:	001-07141	Status:	PR	Insp. Status:	EI
Facility ID:	478681	Type:	OFF-	API Number:	-	Status:	AC	Insp. Status:	EI

Environmental					
Waste Management:					
Type	Management	Condition	GPS (Lat) (Long)		
Comment	No stockpiled soil on location.				
Corrective Action					Date:
Spill/Remediation:					
Comment:	A small excavation is open at the spill location. Staining was observed within the excavation and outside the excavation, outside of the fencing boundaries.				
Corrective Action:	In accordance with 913.d.(1) Operator will investigate impacts to soil, Groundwater, and surface water as soon as the impacts are discovered.				Date: 02/29/2024
Emission Control Burner (ECB):					
Comment:					
Pilot: Wildlife Protection Devices (fired vessels):					
Attached Documents					
You can go to COGCC Images (https://cogcc.state.co.us/weblink/) and search by document number:					
Document Num	Description	URL			
403698427	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6442942			
697602268	Photolog	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6442931			