

Little Beaver Unit TB Photo Log

Location ID: 451505

February 15, 2024

Figure No.:
1

Title:
Stained Soils removed [ref photo 33 from inspection photos]




Figure No.:
2

Title:
Capped piping [ref photo 6 from inspection photos]



Figure No.:
3

Title:
Capped piping (2) [ref photo 7 from inspection photos]



Figure No.:
4

Title:
Capped pipe [ref photo 29 from inspection photos]



Figure No.:
5

Title:
Capped pipe [ref photo 29 from inspection photos]



Figure No.:
6

Title:
Capped pipe [ref photo 40 from inspection photos]



Figure No.:
7

Title:
Bird nesting removed. Ref inspection photo 44



Figure No.:
8

Title:
Ref inspection photo 24



Figure No.:
9

Title:
Ref inspection photo 30




Figure No.:
10

Title:
Ref inspection photo 31



Figure No.:
11

Title:
Ref inspection photo 34




Figure No.:
12

Title:
Ref inspection photo 34



Figure No.:
13

Title:



Figure No.:
14

Title:
Monitoring well cap installed



Figure No.:
15

Title:



Figure No.:
16

Title:



Figure No.:
17

Title:
Pipes secured, oily waste removed. (see inspection photo 46)



Figure No.:
18

Title:
Oily waste removed



Figure No.:
19

Title:



Figure No.:
20

Title:
Excavation area backfilled.



Figure No.:
21

Title:



Figure No.:
22

Title:



Figure No.:
23

Title:



Figure No.:
24

Title:



Figure No.:
25

Title:



Figure No.:
26

Title:



Figure No.:
27

Title:



Figure No.:
28

Title:



Figure No.:
29

Title:



Figure No.:
30

Title:



Figure No.:
31

Title:



Figure No.:
32

Title:



Figure No.:
33

Title:

