

Final Reclamation Inspection

February 29th, 2024

Operator: Simcoe LLC - 10749

Location ID: 333510

Inspection Document #: 714000496

La Plata County, CO

Township: SENE 2 33N 10W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Frank Davis B 2
Location ID: 333510



2/29/24
+37.135875,-107.897695
186° S



2/29/24
+37.135504,-107.897818
204° SW

FRANK DAVIS B 2
SINCOE LLC
ELEVATION: 6250 API #: 06-067-08408 DWR #: 70452-F
NAME OF TRIBE: N/A LEASE TYPE: FEE
LEASE #: N/A CA#: C0C56212
SURFACE LOCATION: SENE SEC 2 - T33N - R10W 1690' FML 1100' FEL
BOTTOM HOLE LOCATION: SAME AS SURFACE LOCATION
LATITUDE: 37.13564249 LONGITUDE: -107.8979927
NEAREST ADDRESS: 6531 CR 213
CONTROL CENTER 24 HR. PHONE #: 970-247-6916
EMERGENCY CONTACT #: 911

Photo 1. View of the disturbance facing center from the entrance.

Inspection Photos
Location Name: Frank Davis B 2
Location ID: 333510



Photo 2. View of trash observed in the southern interim reclamation/fill slope area.

Inspection Photos
Location Name: Frank Davis B 2
Location ID: 333510



2/29/24
+37 135321, -107 897912
233° SW



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. View of additional bits of trash observed in the southern edge of the disturbance.

Inspection Photos
Location Name: Frank Davis B 2
Location ID: 333510



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. View of the western interim reclamation area facing northwest.

API #: 067-08408

Inspection Photos
Location Name: Frank Davis B 2
Location ID: 333510



Photo 5. View of unused equipment observed on location.



Inspection Photos
Location Name: Frank Davis B 2
Location ID: 333510





Photo 6. View of gully erosion forming along the access road.



Inspection Photos
Location Name: Frank Davis B 2
Location ID: 333510



Photo 7. View of culvert that is not installed has not been installed or maintained in accordance with good engineering practices and causing severe gully erosion on the eastern edge of the access road.

Inspection Photos
Location Name: Frank Davis B 2
Location ID: 333510



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 8. View of culvert that is full of sediment and has not been installed or maintained in accordance with good engineering practices and causing erosion moving east off of the access road.

API #: 067-08408

Inspection Photos
Location Name: Frank Davis B 2
Location ID: 333510



2/29/24
+37.136741,-107.895349
221° SW



2/29/24
+37.136741,-107.895349
200° S

Photo 8. View of rill erosion observed on the western edge of the access road. No installed stormwater BMPs were observed in this location.


Inspection Photos
Location Name: Frank Davis B 2
Location ID: 333510



2/29/24

+37.138313, -107.894936

193° S



2/29/24

+37.138143, -107.895045

230° SW



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 9. View of severe rutting and sediment transport observed at the access road entrance point. No installed stormwater BMPs were observed in this area.

API #: 067-08408

Inspection Photos
Location Name: Frank Davis B 2
Location ID: 333510

2/29/24
+37.136631,-107.895376
100° E



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 10. View of the reference comprised of kochia, sagebrush and juniper.

API #: 067-08408