

Inspection Photos
Location Name: UPRR HABEL 1-35
Location ID: 319728



Photo #1 tanks and berm that needs maintained.



Photo #2 base of containment eroded under tanks.

Inspection Photos
Location Name: UPRR HABEL 1-35
Location ID: 319728




Photo #3 Stained soil under load-out line.



Photo #4 Separator.

Inspection Photos
Location Name: UPRR HABEL 1-35
Location ID: 319728



Photo #5 Pump jack.