

Inspection Photos
Location Name: Fonte 33-21
API Number: 125-09192



1. Well sign at CR and access two track.



2. Rig sign at CR and access two track.

Inspection Photos
Location Name: Fonte 33-21
API Number: 125-09192



3. Excell Services Rig #5 on well.



4. Power Swivel hung and running to drill the cement out of production casing.