

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/01/2024

Submitted Date:

03/05/2024

Document Number:

698601629**FIELD INSPECTION FORM**Loc ID 304952 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10699Name of Operator: OWN RESOURCES OPERATING LLCAddress: 305 S RIDGE STREET #6279City: BRECKENRIDGE State: CO Zip: 80424**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:15 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Dolezal, Pat	970-332-3585	pat.dolezal@ownresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
277059	WELL	PR	01/01/2022	GW	125-09192	FONTE 33-21	SI

General Comment:Rig and well repair inspection.

Location

Lease Road:			
Type	Access		
comment:	Two track off maintained County Road. Active agricultural cropland with seasonal access to well location.		
Corrective Action		Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	Well sign located at wellhead.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Rig information sign posted at CR and access road.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Well sign posted at CR and access road.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Emergency contact information posted on well signs.

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Stock panel fencing around surface equipment at well location.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:	Horsehead removed for work-over.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Pump Jack Power and Control Panel.		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric Motor.		
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	277059	Type:	WELL	API Number:	125-09192	Status:	PR	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____									
Comment: Well shut in for casing repair work.									
Corrective Action: _____ Date: _____									
Workover									
Comment: Excell Services LLC, Workover Rig #5 is currently rigged up on well for well casing repair work. Pump Jack Horsehead removed. Rods and tubing have been removed from wellbore. Crew is currently running power swivel to drill out cement and CICR after pumping cement in the annulus space. When the cement is drilled out we will load and pressure test well production casing to verify repair. Service Rig sign at CR intersection. Rig floor and walkway safety barriers and equipment in use. Personal PPE in use.									
Corrective Action: _____ Date: _____									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No stormwater issues noted at time of inspection.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698601731	Inspection photos.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6454516