

## Inspection Photos

Location Name: CAERUS PICEANCE LLC CLEM 15-14 (PA15) Pad

Location #: 324017



Photo # 8330 From entrance to location



Photo # 8331 Location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC CLEM 15-14 (PA15) Pad

Location #: 324017



Photo # 8332 Location



Photo # 8333 Location





## Inspection Photos

Location Name: CAERUS PICEANCE LLC CLEM 15-14 (PA15) Pad

Location #: 324017



Photo # 8334 Location



Photo # 8335 Location



## Inspection Photos

Location Name: CAERUS PICEANCE LLC CLEM 15-14 (PA15) Pad

Location #: 324017



Photo # 8336 Debris