

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/28/2024

Submitted Date:

02/28/2024

Document Number:

699505531**FIELD INSPECTION FORM**Loc ID 319035 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 74165Name of Operator: RENEGADE OIL & GAS COMPANY LLCAddress: 6155 S MAIN STREET #225City: AURORA State: CO Zip: 80016**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:17 Number of Comments10 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Burn, Diana		diana.burn@state.co.us	
Brown, Kari		kari.oakman@state.co.us	
Leonard, Mike		mike.leonard@state.co.us	
Graber, Nikki		nikki.graber@state.co.us	
Ingvie, Ed	(303) 680-4725	ed@renegadeoilandgas.com	All Inspections
Silver, Randy		randy.silver@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
242749	WELL	SI	04/01/2023	GW	123-10540	NECKIEN 1	SI

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Gas meter run needs calibration		
Corrective Action:	Calibrate gas metering equipment annually to comply with rule 430.d.(1).	Date:	03/06/2024
Type	OTHER		
Comment:	No stormwater containment under equipment, delinquent per previous inspection Document # 699505482, open top tank is full with possibility of contamination from precipitation.		
Corrective Action:	Implement BMP following good engineering practices to minimize contact with stormwater and precipitation. 1002.f.(2)B	Date:	02/21/2024
Type	OTHER		
Comment:	Contaminated soil needs to be removed from location, additional contaminated soil was discovered at time of inspection.		
Corrective Action:	For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 905.e.	Date:	03/06/2024
Type	OTHER		
Comment:	Rig tank does not have wildlife netting		
Corrective Action:	Install or repair wildlife protection equipment. rule 608.a.(13)	Date:	03/06/2024
Type	OTHER		
Comment:	Lease road has not been maintained, overgrown with vegetation.		
Corrective Action:	Repair and maintain lease road to comply with rule 204.	Date:	03/06/2024
Type	OTHER		
Comment:	Gas meter run is not calibrated, flow line appears to be in close position. COGCC data shows 283 Gas produced on 3/2023 and 283 gas flared, No record of approval for flaring at this sight per ECMC data. Contact COGCC engineering.		
Corrective Action:	Comply with rule 903.a.(1)	Date:	02/29/2024
Type	OTHER		
Comment:	Equipment on location was never grounded per previous inspection document # 699505482		
Corrective Action:	Design all equipment to prevent accumulation of static charge per Rule 608.d.	Date:	02/22/2024
Type	OTHER		
Comment:	No wellhead sign on well		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	03/06/2024
Type	OTHER		
Comment:	Gas meter run is not calibrated, flow line appears to be in close position. COGCC data shows 283 Gas produced on 3/2023 and 283 gas flared,		
Corrective Action:	Measure gas per Rule 430.	Date:	03/06/2024

Type	OTHER				
Comment:	Unused rig tank, rig pump, and automation equipment need to be removed from location				
Corrective Action:	Comply with Rule 606			Date:	03/06/2024

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:					
Type	LOCATION				
Comment:	4' barb wire				
Corrective Action:					Date:

Equipment:				corrective date	
Type: Bradenhead	# 1				
Comment:	Plumbed to surface				
Corrective Action:			Date:		
Type: Plunger Lift	# 1				
Comment:					
Corrective Action:			Date:		
Type: Horizontal Heated Separator	# 1				
Comment:					
Corrective Action:			Date:		
Type: Bird Protectors	# 1				
Comment:					
Corrective Action:			Date:		
Type: Deadman # & Marked	# 4				
Comment:					
Corrective Action:			Date:		
Type: Gas Meter Run	# 1				
Comment:					
Corrective Action:			Date:		
Type: Ancillary equipment	# 1				
Comment:	automation				
Corrective Action:			Date:		

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLS	STEEL AST		,	
Comment:						

Corrective Action:		Date:	
--------------------	--	-------	--

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
			Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					
				Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	shares containment with oil tank			
Corrective Action:				
			Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 242749 Type: WELL API Number: 123-10540 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: SI

Corrective Action: _____

Date: _____

BradenHeadDate of Last Brhd Test: 11/05/2023Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0Fluid Type: NONEEnd Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

COGCC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary</p> <p>On 2/28/24 I, Inspector Justin Medina conducted an on-site inspection at:</p> <p>Well Name- Neckien 1</p> <p>Company Name- Renegade oil and gas Company LLC</p> <p>API- 05-123-10540</p> <p>In Weld County Colorado.</p> <p>While there, I observed SI well</p> <p>This is a follow up inspection from document # 699505482 Corrective Actions are Delinquent</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Unused equipment. Rule 606. 3/6/24</p> <p>Contaminated soil. Rule 905.e. 3/6/24</p> <p>Measure gas. Rule 430. 3/6/24</p> <p>Flaring . Rule 903.a.(1) 2/29/24</p> <p>Gas Meter run Calibration. Rule 430.d.(1)</p> <p>Stormwater control measures. Rule 1002.f.(2) b. 2/21/24</p> <p>Grounding/static discharge. Rule 608.d. 2/22/24</p> <p>Wellhead sign. Rule 605.d. 3/6/24</p> <p>Wildlife netting. Rule 608.a.(13). 3/6/24</p> <p>Lease road maintenance. Rule 204. 3/6/24</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.</p> <p>At time of inspection weather conditions were cold, calm, clear, recent snow.</p> <p>This is a summary of inspection report.</p>	medinaj	02/28/2024

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
403702826	INSPECTION SUBMITTED	http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6447579
699505532	inspection pictures	http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6447555