

Final Reclamation and Stormwater Inspection

Date: 02/29/2024

Operator: NOBLE ENERGY INC - 100322

Location ID: 328321

Inspection Document #: 708200947

Weld County, CO

Dylan Edwardson
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: N36 - 16 Pad
Location ID: 328321



Photo 1. Gully erosion on the north side of the former tank battery location.

Inspection Photos
Location Name: N36 - 16 Pad
Location ID: 328321



Photo 2. The former tank battery does not appear to have been reclaimed per Rule 1004.

Inspection Photos
Location Name: N36 - 16 Pad
Location ID: 328321



Photo 3. The former tank battery does not appear to have been reclaimed per Rule 1004.

Inspection Photos
Location Name: N36 - 16 Pad
Location ID: 328321



Photo 3. Eastern side of the former tank battery location. Erosion degradation pictured.

Inspection Photos
Location Name: N36 - 16 Pad
Location ID: 328321



Photo 5. Close up of erosion degradation on the east side of the location.

Inspection Photos
Location Name: N36 - 16 Pad
Location ID: 328321



Photo 6. Erosion degradation occurring on the southeast corner of the location.

Inspection Photos
Location Name: N36 - 16 Pad
Location ID: 328321



Photo 7. Taken from the southern end of the former tank battery location. The location does not appear to have been reclaimed per Rule 1004.

Inspection Photos
Location Name: N36 - 16 Pad
Location ID: 328321



Photo 8. Erosion degradation occurring on the southwest corner of the location.

Inspection Photos
Location Name: N36 - 16 Pad
Location ID: 328321




Photo 9. Mouse/rat holes not backfilled, located on the southwest portion of the location.



Photo 10. Erosion degradation occurring on the western portion of the location.

Inspection Photos
Location Name: N36 - 16 Pad
Location ID: 328321



2/29/24, 1:09 PM
227° SW
ECMC

Photo 11. Erosion degradation occurring on the western portion of the location.

Inspection Photos
Location Name: N36 - 16 Pad
Location ID: 328321



Photo 12. Continued from Photo 11. Erosion degradation occurring on the western portion of the location.



Photo 13. Erosion degradation occurring on the western portion of the location.

Inspection Photos
Location Name: N36 - 16 Pad
Location ID: 328321



Photo 14. Taken feast of the former location. Erosion degradation occurring outside of the permitted location will need to be properly stabilized and repaired.

Inspection Photos
Location Name: N36 - 16 Pad
Location ID: 328321



Photo 15. Road base material observed within the former access road footprint.

Inspection Photos
Location Name: N36 - 16 Pad
Location ID: 328321



Photo 16. Taken from the northern portion of the former well location. It does not appear the well location has been reclaimed per Rule 1004 with evidence of bare soils and undesirable vegetation.

Inspection Photos
Location Name: N36 - 16 Pad
Location ID: 328321



Photo 17. Taken from the southern portion of the former well location; see comments in Photo 16.