

Inspection Photos
Location Name: Silverback 36-A PAD
Location ID: 443555



Photo 1 – Gas Meter House



Photo 2 – Equipment

Inspection Photos
Location Name: Silverback 36-A PAD
Location ID: 443555



Energy and Carbon Management Commission
40 97307, -104 27089, 5234.4ft
03/05/2024 12:35:38



Energy and Carbon Management Commission
40-97306, -104 2711, 5248.2ft
03/05/2024 12:39:35

Photo 3 – Day Tanks removed from Location

Photo 4 – Unmarked Riser

Inspection Photos
Location Name: Silverback 36-A PAD
Location ID: 443555




Photo 5 – Unmarked Riser



Photo 6 – Flare

Inspection Photos
Location Name: Silverback 36-A PAD
Location ID: 443555



Photo 7 – Pumping Unit



Photo 8 – Stained Soil at Gas Engine

Inspection Photos
Location Name: Silverback 36-A PAD
Location ID: 443555



Photo 9 – Stained Soil at Gas Engine

Photo 10 – Maintenance Tank

Inspection Photos
Location Name: Silverback 36-A PAD
Location ID: 443555



Photo 13 – ECDs

Photo 14 – Separators