

# Interim Reclamation and Stormwater Inspection

Date: 02/29/2024

Operator: NOBLE ENERGY INC - 100322

Location ID: 327777

Inspection Document #: 708200952

Weld County, CO

Dylan Edwardson  
Reclamation Specialist, ECMC



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

Inspection Photos

Location Name: Bernhardt State PC N 36-17

Tank

Location ID: 327777



**Photo 1.** Debris within tank battery secondary containment.



Inspection Photos

Location Name: Bernhardt State PC N 36-17

Tank

Location ID: 327777



**Photo 2.** Debris observed outside and south of tank battery. Remove or repair/reinstall sign.



# Inspection Photos

Location Name: Bernhardt State PC N 36-17

Tank

Location ID: 327777



**Photo 3.** Southwest corner of location. Erosion degradation appears to have been repaired previously; no apparent stormwater control measures/BMPs observed to manage stormwater runoff. Bare soils require additional reclamation activities to stabilize the soils.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Number: 708200952



Inspection Photos

Location Name: Bernhardt State PC N 36-17

Tank

Location ID: 327777



**Photo 4.** Stained soil observed at southern vertical steel tank.



Inspection Photos

Location Name: Bernhardt State PC N 36-17

Tank

Location ID: 327777



**Photo 5.** Porta john not properly anchored.



# Inspection Photos

Location Name: Bernhardt State PC N 36-17

Tank

Location ID: 327777



**Photo 6.** Western portion of location. Erosion degradation appears to have been repaired previously; no apparent stormwater control measures/BMPs observed to manage stormwater runoff. Bare soils require additional reclamation activities to stabilize the soils.

# Inspection Photos

Location Name: Bernhardt State PC N 36-17

Tank

Location ID: 327777



**Photo 7.** Western portion of location. Erosion degradation appears to have been repaired previously; no apparent stormwater control measures/BMPs observed to manage stormwater runoff. Bare soils require additional reclamation activities to stabilize the soils.



# Inspection Photos

Location Name: Bernhardt State PC N 36-17

Tank

Location ID: 327777



**Photo 8.** Western portion of location. Erosion degradation appears to have been repaired previously; no apparent stormwater control measures/BMPs observed to manage stormwater runoff. Bare soils require additional reclamation activities to stabilize the soils.



Inspection Photos

Location Name: Bernhardt State PC N 36-17

Tank

Location ID: 327777



**Photo 9.** Western portion of location. Erosion degradation appears to have been repaired previously; no apparent stormwater control measures/BMPs observed to manage stormwater runoff. Bare soils require additional reclamation activities to stabilize the soils.