

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/05/2024

Submitted Date:

03/06/2024

Document Number:

708903211

FIELD INSPECTION FORMLoc ID 334660 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

29 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|---|---------|
| , Caerus | | COGCC.inspections@caerus oilandgas.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------------|-------------|
| 283221 | WELL | PR | 06/15/2008 | GW | 045-11910 | SHIDELER 25-8 (E30E) | PR |
| 283222 | WELL | PR | 06/12/2008 | GW | 045-11909 | SHIDELER 25-1C (E30E) | PR |
| 283223 | WELL | PR | 05/26/2008 | GW | 045-11908 | SHIDELER 25-8C (E30E) | PR |
| 283224 | WELL | PR | 05/26/2008 | GW | 045-11905 | SHIDELER 30-11B (E30E) | PR |
| 283225 | WELL | PR | 06/02/2008 | GW | 045-11903 | SHIDELER 30-2C (E30E) | PR |
| 283226 | WELL | PR | 05/30/2008 | GW | 045-11902 | SHIDELER 30-3C (E30E) | PR |
| 283229 | WELL | PR | 06/06/2008 | GW | 045-11900 | SHIDELER 30-6B (E30E) | PR |

General Comment:**CECMC Inspection Report Summary**

On 03/05/2024 at approximately 10:02 hours, I, Compliance Specialist, Wayne Smelser
Conducted a follow up inspection at CAERUS PICEANCE LLC SHIDELER 25-8 (E30E) Pad.
Location # 334660 in Garfield County Colorado.

Please refer to inspection 708903032 conducted on 02/08/2024, previous corrective action has been completed.

Location is within High Priority/Density/Black Bear Habitat areas.

While there, I observed normal production operations.

This is a summary of inspection report.

Split pad/Shared facilities with location # 334630

Location**Lease Road:**

| | | | |
|-------------------|--------|-------|--|
| Type | Access | | |
| comment: | | | |
| Corrective Action | L | Date: | |

Overall Good: ☐**Signs/Marker:**

| | | | |
|--------------------|--|-------|--|
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | OTHER | | |
| Comment: | Sign at entrance to location | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | OTHER | | |
| Comment: | Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks. | | |
| Corrective Action: | | Date: | |
| Type | CONTAINERS | | |
| Comment: | Chemical tank | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment: 911/970-285-2615

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

| | | | |
|--------------------|--------------|-------|--|
| Type | TANK BATTERY | | |
| Comment: | Bollards | | |
| Corrective Action: | | Date: | |

| | | | | | |
|--------------------|---|--|--|-------|--|
| Type | LOCATION | | | | |
| Comment: | Barbed wire fence Fence showing some signs of disrepair in areas | | | | |
| Corrective Action: | | | | Date: | |

| | | | | |
|-----------------------------------|---|--|-------|-----------------|
| Equipment: | | | | corrective date |
| Type: Bradenhead | # 7 | | | |
| Comment: | Pressure transducers located on all bradenhead. All bradenhead valves are accessible. | | | |
| Corrective Action: | | | Date: | |
| Type: Bird Protectors | # 8 | | | |
| Comment: | | | | |
| Corrective Action: | | | Date: | |
| Type: Ancillary equipment | # 1 | | | |
| Comment: | Chemical tank | | | |
| Corrective Action: | | | Date: | |
| Type: Other | # 1 | | | |
| Comment: | Bear proof trash container | | | |
| Corrective Action: | | | Date: | |
| Type: Gas Meter Run | # 15 | | | |
| Comment: | | | | |
| Corrective Action: | | | Date: | |
| Type: Horizontal Heated Separator | # 15 | | | |
| Comment: | | | | |
| Corrective Action: | | | Date: | |
| Type: Other | # 1 | | | |
| Comment: | Telemetry | | | |
| Corrective Action: | | | Date: | |
| Type: Emission Control Device | # 1 | | | |
| Comment: | | | | |
| Corrective Action: | | | Date: | |
| Type: Plunger Lift | # 7 | | | |
| Comment: | All wells on plunger lift | | | |
| Corrective Action: | | | Date: | |

| | | | | | |
|-------------------------|---|----------|-----------|---------|--------|
| Tanks and Berms: | | | | | |
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| METHANOL | 1 | 1000 GAL | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

| | |
|-----------------|----------|
| Paint | |
| Condition | Adequate |
| Other (Content) | |

| | | | | | | |
|--|----------|---------------------|---------------------|-------------|--------|-------|
| Other (Capacity) | | | | | | |
| Other (Type) | | | | | | |
| Berms | | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | | |
| Metal | Adequate | Walls Sufficient | | | | |
| Comment: Centralized containment | | | | | | |
| Corrective Action: | | | | | | Date: |
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| CONDENSATE | 2 | 500 BBLs | STEEL AST | | , | |
| Comment: Tanks equipped with telemetry | | | | | | |
| Corrective Action: | | | | | | Date: |
| Paint | | | | | | |
| Condition | Adequate | | | | | |
| Other (Content) | | | | | | |
| Other (Capacity) | | | | | | |
| Other (Type) | | | | | | |
| Berms | | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | | |
| Metal | Adequate | Walls Sufficient | | | | |
| Comment: Centralized containment | | | | | | |
| Some snow in containment but appears all holes in containment liner observed in previous inspection have been patched. | | | | | | |
| Corrective Action: | | | | | | Date: |
| Venting: | | | | | | |
| Yes/No | NO | | | | | |
| Comment: | | | | | | |
| Corrective Action: | | | | | | Date: |
| Flaring: | | | | | | |
| Type | | | | | | |
| Comment: | | | | | | |
| Corrective Action: | | | | | | Date: |

| Inspected Facilities | | | | | | |
|-----------------------|---------------------------------|-------|------|-----------------------|------------|------------------|
| Facility ID: | 283221 | Type: | WELL | API Number: 045-11910 | Status: PR | Insp. Status: PR |
| Producing Well | | | | | | |
| Comment: | Producing, well on plunger lift | | | | | |
| Corrective Action: | | | | | | Date: |
| Facility ID: | 283222 | Type: | WELL | API Number: 045-11909 | Status: PR | Insp. Status: PR |
| Producing Well | | | | | | |
| Comment: | Producing, well on plunger lift | | | | | |
| Corrective Action: | | | | | | Date: |
| Facility ID: | 283223 | Type: | WELL | API Number: 045-11908 | Status: PR | Insp. Status: PR |
| Producing Well | | | | | | |
| Comment: | Producing, well on plunger lift | | | | | |
| Corrective Action: | | | | | | Date: |
| Facility ID: | 283224 | Type: | WELL | API Number: 045-11905 | Status: PR | Insp. Status: PR |
| Producing Well | | | | | | |
| Comment: | Producing, well on plunger lift | | | | | |
| Corrective Action: | | | | | | Date: |
| Facility ID: | 283225 | Type: | WELL | API Number: 045-11903 | Status: PR | Insp. Status: PR |
| Producing Well | | | | | | |
| Comment: | Producing, well on plunger lift | | | | | |
| Corrective Action: | | | | | | Date: |
| Facility ID: | 283226 | Type: | WELL | API Number: 045-11902 | Status: PR | Insp. Status: PR |
| Producing Well | | | | | | |
| Comment: | Producing, well on plunger lift | | | | | |
| Corrective Action: | | | | | | Date: |
| Facility ID: | 283229 | Type: | WELL | API Number: 045-11900 | Status: PR | Insp. Status: PR |
| Producing Well | | | | | | |
| Comment: | Producing, well on plunger lift | | | | | |
| Corrective Action: | | | | | | Date: |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|----------------------------------|
| | | | | Material Handling And Spill Prevention | | Chemical tank containment |
| Gravel | | | | | | Sparse to none |
| Compaction | | | | | | Large amount of light compaction |
| | | Gravel | | | | Sparse to none |
| | | Compaction | | | | Light compaction |

Comment: Places with sparse to no gravel & light compaction are present on location. Sparse/no gravel and light compaction could lead to future stabilization and tracking issues.

Some signs of lack of stabilization/compaction starting to develop in small areas of location.

Limited Stormwater inspection due to snow.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment | User | Date |
|--|----------|------------|
| Split pad/Shared facilities with location # 334630 | smelserw | 03/06/2024 |
| Please refer to Stormwater for comments | | |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---|---|
| 708903212 | Inspection 708903211 Stormwater photo log | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6456358 |
| 708903213 | Inspection 708903211 photo log | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6456359 |