

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/06/2024

Submitted Date:

03/06/2024

Document Number:

708903216

FIELD INSPECTION FORM

Loc ID 420296	Inspector Name: Smelser, Wayne	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: 96850 Name of Operator: TEP ROCKY MOUNTAIN LLC Address: 1058 COUNTY ROAD 215 City: PARACHUTE State: CO Zip: 81635				Findings: 40 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:			
Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
420317	WELL	PR	04/18/2012	GW	045-20119	CBS 31C-21-692	PR
420318	WELL	PR	03/23/2012	GW	045-20120	CBS 32B-21-692	PR
420319	WELL	PR	04/18/2012	GW	045-20121	CBS 41C-21-692	PR
420320	WELL	PR	04/18/2012	GW	045-20122	CBS 31B-21-692	PR
420321	WELL	PR	04/18/2012	GW	045-20123	CBS 41D-21-692	PR
420322	WELL	PR	03/22/2012	GW	045-20124	CBS 41B-21-692	PR
420323	WELL	PR	04/18/2012	GW	045-20125	CBS 31D-21-692	PR
420324	WELL	PR	03/23/2012	GW	045-20126	CBS 42D-21-692	PR
420325	WELL	PR	03/22/2012	GW	045-20127	CBS 32D-21-692	PR
420326	WELL	PR	03/23/2012	GW	045-20128	CBS 42B-21-692	PR

General Comment: <p>CECMC Inspection Report Summary On 03/06/2024 at approximately 15:08 hours, I, Compliance Specialist, Wayne Smelser Conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC Circle B Land Tract 5 21-692 Pad. Location # 420296 in Garfield County Colorado. Location is within High Priority/Density/Black Bear Habitat areas. Location is in close proximity to Rule 411a Surface Water External Buffer. While there, I observed normal production operations.</p> <p>During this inspection the following compliance issues were observed:</p> <p>1. Stormwater - Chemical containment approximately 3/4 full of fluid/failure to maintain chemical BMP with a CA date of 03/09/2024</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules. This is a summary of inspection report.</p>

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	CONTAINERS		
Comment:	Chemical tank		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Tank label on non heated produced water tank missing required info		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911/970-285-9377	
Corrective Action:		Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	Small amount of weeds in secondary containment		
Corrective Action:		Date:	
Type	DEBRIS		
Comment:	Dead weeds/debris - please refer to photo log		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Cattle panels		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Liquid nitrogen tank - hog panels		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Barbed wire fence		
Corrective Action:		Date:	

Equipment:				corrective date
Type: Ancillary equipment	# 1			
Comment:	Chemical tank			
Corrective Action:		Date:		
Type: Horizontal Heated Separator	# 10			
Comment:				
Corrective Action:		Date:		
Type: Ancillary equipment	# 1			
Comment:	Liquid nitrogen tank			
Corrective Action:		Date:		
Type: Gas Meter Run	# 10			
Comment:				
Corrective Action:		Date:		
Type: Bird Protectors	# 9			
Comment:				
Corrective Action:		Date:		
Type: Bradenhead	# 10			
Comment:	Taylor plugs located on all bradenhead. All bradenhead valves are accessible.			
Corrective Action:		Date:		
Type: Plunger Lift	# 10			
Comment:	All wells on plunger lift			
Corrective Action:		Date:		

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	500 BBLS	STEEL AST		,	
Comment:	Tank not equipped with telemetry					
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent			
Comment:	Centralized containment				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	500 BBLs	STEEL AST		,
Comment:	Tank equipped with telemetry				
Corrective Action:				Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent			
Comment:	Centralized containment				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	500 BBLs	HEATED STEEL AST		,
Comment:	Tank not equipped with telemetry				
Corrective Action:				Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent			
Comment:	Centralized containment				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	500 BBLs	HEATED STEEL AST		,

Comment:		2 of the 3 tanks are equipped with telemetry				
Corrective Action:					Date:	
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficent				
Comment:		Centralized containment				
Corrective Action:					Date:	
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	
Flaring:						
Type						
Comment:						
Corrective Action:					Date:	

Inspected Facilities									
Facility ID:	420317	Type:	WELL	API Number:	045-20119	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	420318	Type:	WELL	API Number:	045-20120	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	420319	Type:	WELL	API Number:	045-20121	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	420320	Type:	WELL	API Number:	045-20122	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	420321	Type:	WELL	API Number:	045-20123	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	420322	Type:	WELL	API Number:	045-20124	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	420323	Type:	WELL	API Number:	045-20125	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	420324	Type:	WELL	API Number:	045-20126	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			

Facility ID: 420325 Type: WELL API Number: 045-20127 Status: PR Insp. Status: PR

Producing Well

Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	

Facility ID: 420326 Type: WELL API Number: 045-20128 Status: PR Insp. Status: PR

Producing Well

Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Fail	Failure to maintain chemical BMP
		Compaction				
Gravel						Sparse to none in some areas
Compaction						Light compaction in some areas
Other						Small amount of erosion on slope behind separators
		Ditches				
Rip Rap						
Ditches						
Berms						
		Gravel				Sparse to none
		Culverts				

Comment: 1. Chemical containment approximately 3/4 full of fluid/failure to maintain chemical BMP/BMP insufficient to contain possible spill.

Corrective Action: Comply with CECMC Stormwater rules

Date: 03/09/2024

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Please refer to Stormwater for observed compliance issue.	smelserw	03/06/2024

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708903218	Inspection 708903216 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6456435
708903219	Inspection 708903216 Stormwater photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6456436