

**KT Resources LLC
Ant Hill Unit 21-22
Location ID: 398705**



As signs are replaced additional information is required

Inadequate wildlife protection

KT Resources LLC
Ant Hill Unit 21-22
Location ID: 398705



Replace illegible or damaged labels as required

No visible display of gas meter calibration

**KT Resources LLC
Ant Hill Unit 21-22
Location ID: 398705**



Erosion and sediment migration



Erosion and sediment migration

**KT Resources LLC
Ant Hill Unit 21-22
Location ID: 398705**



Location from Southwest corner



Location from Northwest corner

**KT Resources LLC
Ant Hill Unit 21-22
Location ID: 398705**



Location from Northeast corner



Location from Southeast corner