

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/07/2024

Submitted Date:

03/07/2024

Document Number:

694100302

**FIELD INSPECTION FORM**

Loc ID 479311 Inspector Name: Robinson, Taylor On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1700 LINCOLN ST STE 4550  
City: DENVER State: CO Zip: 80203

**Findings:**

- 7 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	<a href="#">All Inspections</a>
Kuhn, Denny		cogcc@kpk.com	
,		rwatzman@kpk.com	<a href="#">All Inspections</a>

**General Comment:**

This is an environmental inspection for Location ID 479311 Facility 4 UPRR 42 Pan Am AE. Any corrective actions from previous inspections that have not been addressed are still applicable. There was one operator personnel on location at the time of this field inspection. Photos attached to document site conditions.

**Location**

Overall Good:

Emergency Contact Number:

Comment: Soil spoil pile from recent excavation does not have proper signage articulating that soil is contaminated. There are nearby residences to this location.

Corrective Action: Sign not posted or information inaccurate at oil and gas location. Install sign to comply with Rule 605.a.

Date: 03/14/2024

Overall Good:

<b>Spills:</b>					
Type	Area	Volume			
Comment:	This inspection is in regard to an historical release found at the flowline. Approximately 50 cubic yards of contaminated soil have been removed, but an unknown amount remain in situ. Soil samples have been taken on several occasions, including during this inspection, to delineate extent of impacts.				
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.			Date:	04/04/2024

In Containment: No

Comment: This inspection is in regard to historical release found at the flowline. Some contaminated soils have been removed, but an unknown amount remain in situ. Soil samples have been taken on several occasions to delineate extent of impacts.

Multiple Spills and Releases?

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: This inspection was conducted in response to an historical release found at the flowline. Approximately 50 cubic yards of contaminated soil have been removed, but an unknown amount remain in situ. Soil samples have been taken on several occasions, including during this inspection, to delineate extent of impacts.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
KPK personnel was on site to be witnessed by ECMC staff during sample collection. Three sample were taken during this inspection including one sample at the North, East, and West sidewalls.	robinsotl	03/07/2024
No Base sample was taken due to the presence of groundwater or at the South sidewall as this wall has so far been found to be clean and no further excavation in that direction is planned. However, further excavation is planned in the East and West directions due to elevated PID readings in those directions. PID readings were the following North - 1.0, East - 430.8, West - 321.8.		
The current excavation is approximately 12ft long x 10ft wide x 9ft deep and is surrounded by orange construction fencing.		
Excavation is approximately 30-40ft NE of nearest domestic residence.		

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694100303	photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6457563">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6457563</a>