

**KT Resources LLC  
Ant Hill Unit Wyatt 36-13  
Location ID: 316347**



**Erosion and sediment migration**

**Erosion and sediment migration**

KT Resources LLC  
Ant Hill Unit Wyatt 36-13  
Location ID: 316347



As signs are replaced additional information is required



Debris

**KT Resources LLC  
Ant Hill Unit Wyatt 36-13  
Location ID: 316347**



**Erosion and sediment migration**




**Erosion and sediment migration**

KT Resources LLC  
 Ant Hill Unit Wyatt 36-13  
 Location ID: 316347



Relief rain protection missing



Calibration overdue

**KT Resources LLC  
Ant Hill Unit Wyatt 36-13  
Location ID: 316347**



**Erosion and sediment migration**



**Sediment migration**

**KT Resources LLC  
Ant Hill Unit Wyatt 36-13  
Location ID: 316347**



**Sediment migration**



**Sediment migration**

**KT Resources LLC  
Ant Hill Unit Wyatt 36-13  
Location ID: 316347**



Mar 6, 2024 at 1:00:39 PM



Mar 6, 2024 at 1:04:58 PM

**Location from Northwest corner**

**Location from Northeast corner**

**KT Resources LLC  
Ant Hill Unit Wyatt 36-13  
Location ID: 316347**



**Location from Southeast corner**

**Location from Southwest corner**