

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/23/2024

Submitted Date:

03/01/2024

Document Number:

701103931**FIELD INSPECTION FORM**Loc ID 467272 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

4 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
, Caerus Piceance		COGCC.inspections@caerusoilandgas.com	Piceance inspections only

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
467503	WELL	PR	09/20/2021	GW	103-12372	ELU J14 FED 22C-14-496	EG
486045	SPILL OR RELEASE	AC	02/23/2024		-	ELU J14 Flowline Spill	AC

**General Comment:**

Flowline integrity inspection



## Inspected Facilities

Facility ID: 467503 Type: WELL API Number: 103-12372 Status: PR Insp. Status: EG

## Flowline

#2 Type: Sales Line

1 of Lines

## Flowline Description

Flowline Type: Sales Line

Size: 2"

Material: Carbon Steel

Variance:

Age:

Contents:

## Integrity Summary

Failures:

Spills:

Repairs Made:

Coatings:

H2S:

Cathodic Protection:

## Pressure Testing

Witnessed:

Test Result:

Charted:

## COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation☐ 1102. Operations, Maintenance, and Repair☐ 1103. Abandonment

Comment: During inspection a leaking thread was observed. Pumper showed up and shut in the well and call for a roustabout crew to make repairs.

Corrective Action:

Date:

Facility ID: 486045 Type: SPILL OR API Number: - Status: AC Insp. Status: AC

## Flowline

#1 Type: Sales Line

1 of Lines

## Flowline Description

Flowline Type: Sales Line

Size: 2"

Material: Carbon Steel

Variance:

Age:

Contents:

## Integrity Summary

Failures:

Spills:

Repairs Made:

Coatings:

H2S:

Cathodic Protection:

## Pressure Testing

Witnessed:

Test Result:

Charted:

## COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation☐ 1102. Operations, Maintenance, and Repair☐ 1103. Abandonment

Comment: From 19 doc # 403680226  
In the Supplemental Form 19, identify the root cause of the failure and explain how reoccurrence on this pipeline and the other pipelines associated with this facility will be prevented, per Rule 912.d.(3).

Coordinate with ECMC Western Integrity Inspector, Mike Longworth, regarding pipeline excavation, assessment, and repair.

Provide a minimum 48-hours of advance notice to Mike Longworth via email (michael.longworth@state.co.us) prior to pressure testing of equipment.



Corrective Action:	Form 19 (SUPPLEMENTAL) doc # 403690289 has no Root Cause and repair made to prevent reoccuance. No coordination with ECMC Western Integrity Inspector, Mike Longworth, regarding pipeline excavation, assessment, and repair. No notice provide a minimum 48-hours of advance notice to Mike Longworth via email (michael.longworth@state.co.us) prior to pressure testing of equipment. Submit In the Supplemental Form 19, identify the root cause of the failure and explain how reoccurrence on this pipeline and the other pipelines associated with this facility will be prevented, per Rule 912.d.(3). Respond to why no coordination and no notice to test equipment was provided by FIRR (Field Inspection Report Resolution)	Date: 03/08/2024
--------------------	---	------------------

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403705604	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6450844">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6450844</a>
701103932	Flowline integrity inspection 701103931 photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6450838">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6450838</a>
701103933	Thread leaking and bubbling on Fed. 22C-14	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6450839">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6450839</a>