

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/26/2024

Submitted Date:

03/01/2024

Document Number:

701103934

## FIELD INSPECTION FORM

Loc ID 335320 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

3 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus Piceance		COGCC.inspections@caerus oilandgas.com	Piceance inspections only
Schlagenhauf, Mark		mark.schlagenhauf@state.co. us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
485649	SPILL OR RELEASE	AC	12/08/2023		-	P23B Dumpline Leak	AC

**General Comment:**

Flowline integrity inspection

Location

Overall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good: ☐

Spills:

Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Date Run: 3/8/2024 Doc [#701103934]

Page 2 of 3

**Inspected Facilities**Facility ID: 485649 Type: SPILL OR API Number: - Status: AC Insp. Status: AC**Flowline**

#1	Type:	of Lines	
----	-------	----------	--

Flowline Description

Flowline Type:                      Size:                      Material:  
Variance:                      Age:                      Contents:

Integrity Summary

Failures:                      Spills:                      Repairs Made:  
Coatings:                      H2S:                      Cathodic Protection:

Pressure Testing

Witnessed:                      Test Result:                      Charted:

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation    ☐ 1102. Operations, Maintenance, and Repair    ☐ 1103. Abandonment

Comment: [Form 19 doc # 403609757](#)

In the Supplemental Form 19, identify the root cause of the failure and explain how reoccurrence on this pipeline and the other pipelines associated with this facility will be prevented, per Rule 912.d.(3). Coordinate with ECMC Western Integrity Inspector, Mike Longworth, regarding pipeline excavation, assessment, and repair. Provide a minimum 48-hours of advance notice to Mike Longworth via email ([michael.longworth@state.co.us](mailto:michael.longworth@state.co.us)) prior to pressure testing of equipment

Corrective Action: **Form 19 (SUPPLEMENTAL) doc # 403617815 has no Root Cause and repair made to prevent reoccuance.**  
**No coordination with ECMC Western Integrity Inspector, Mike Longworth, regarding pipeline excavation, assessment, and repair.**  
**No notice provide a minimum 48-hours of advance notice to Mike Longworth via email ([michael.longworth@state.co.us](mailto:michael.longworth@state.co.us)) prior to pressure testing of equipment.**  
**Submit In the Supplemental Form 19, identify the root cause of the failure and explain how reoccurrence on this pipeline and the other pipelines associated with this facility will be prevented, per Rule 912.d.(3).**  
**Respond to why no coordination and no notice to test equipment was provided by FIRR (Field Inspection Report Resolution)**

Date: 03/08/2024Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403705605	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6450848">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6450848</a>
701103935	Flowline integrity inspection 701103934 photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6450840">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6450840</a>