

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/27/2024

Submitted Date:

03/01/2024

Document Number:

713600793

FIELD INSPECTION FORM

Loc ID 324804 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 95620

Name of Operator: WESTERN OPERATING COMPANY

Address: 1165 DELAWARE STREET #200

City: DENVER State: CO Zip: 80204

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 4 Number of Comments
- 3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Hart, Dale	719-688-1638	dale@westernoperating.com	
James, Steven	(303) 893-2438	steve@westernoperating.com	
ECMC Complaint		dnr_ogcc.complaint@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
324804	LOCATION	AC			-	KING-PYLES-619S45W 8SWSE	RI

General Comment:

This is a reclamation inspection of the KING-PYLES #4 wellsite and off-site tank battery.
This inspection is in response to complaint #403694753.
See attached photos and additional details within this report.

LocationOverall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:	The well sign is faded and does not meet the signage requirements.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	04/01/2024

Emergency Contact Number:

Comment:			
Corrective Action:		Date:	

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	There are 2 disconnected tanks at the east side of the tank battery that are unused and need to be removed.		
Corrective Action:	Comply with Rule 606.	Date:	04/01/2024

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 324804 Type: LOCATION API Number: - Status: AC Insp. Status: RI**Complaint**

Comment: Complaint is regarding pre-emergent herbicide sprayed on location and onto tumbleweed debris that blew off site into the pasture. On the day of this inspection, there was high wind conditions. There was tumbleweed debris observed along the tank battery fence. There was weed debris observed inside the tank battery fence which had blue die from herbicide application. The tumbleweed debris can be transported off site from wind conditions with a concern of translocating the herbicide with the debris. The weed debris will need to be removed and properly disposed. Avoidance of spraying tumble weed debris shall be taken to avoid potential drift and translocation off-site.

Corrective Action: **Comply with Rule 606 and 1003 for removal of weed debris.**Date: 03/08/2024**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403705198	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6450176
713600794	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6450171